

Incident Report - (Incident UID - IMF/TTK/COI/TIT/25/00073)

Incident Information


Incident UID	IMF/TTK/COI/TIT/25/00073	Category Name	Fire and others
Incident Description	A small fire broke out near the electrical control panel due to a short circuit caused by water seepage during heavy rain. The fire was quickly extinguished by the in-house emergency response team using a CO2 extinguisher.	Status	FinalReportReleased
Site Name	Coimbatore	Department Name	Maintenance
Incident Date & Time	05-Oct-2025 08:00:00 AM	Created On	10-Oct-2025 10:21:53 AM
Reported By	Lalit Aditya Kola		

Sections

Category of incident	<div><div><input checked="" type="radio"/> Fire</div><div><input type="radio"/> Flood</div><div><input type="radio"/> Cyclone</div><div><input type="radio"/> Heavy rain</div><div><input type="radio"/> Epidemic disease</div><div><input type="radio"/> Local threat</div></div>
----------------------	--

Photograph of the incident

Attach: 1
-----------

Attachments


Immediate corrective steps taken

S.No.	Actions	Responsibility	Status	Completion date
1	Power isolated and area secured	Maintenance Supervisor	NA	2025-10-07
2	Electrical inspection conducted and wiring replaced	Electrical Engineer	NA	2025-10-09