

Incident Report - (Incident UID - IMF/TTK/COI/TIT/25/00086)

Incident Information

Incident UID	IMF/TTK/COI/TIT/25/00086	Category Name	Fire and others
Incident Description	A small fire broke out near the electrical control panel due to a short circuit caused by water seepage during heavy rain. The fire was quickly extinguished by the in-house emergency response team using a CO2 extinguisher.	Status	FinalReportReleased
Site Name	Coimbatore	Department Name	25 regression
Incident Date & Time	21-Oct-2025 12:00:00 AM	Created On	23-Oct-2025 06:46:15 PM
Reported By	Mounika Laisetti		

Sections

Category of incident	<input checked="" type="radio"/> Fire <input type="radio"/> Flood <input type="radio"/> Cyclone <input type="radio"/> Heavy rain <input type="radio"/> Epidemic disease <input type="radio"/> Local threat
----------------------	---

Photograph of the incident

Attach: 1

Attachments

Immediate corrective steps taken

S.No.	Actions	Responsibility	Status	Completion date
1	Power isolated and area secured	Maintenance Supervisor	NA	NA
2	Electrical inspection conducted and wiring replaced	Electrical Engineer	NA	NA

Definition:

Injury Type	Level	Definition
Bruise	L1	Blood Clot
Abrasion	L2	Skin Rubbed with Rough Surface
Burn	L3	Skin Burn due to fire, chemical, etc
Laceration	L4	Tear or a cut in the skin
Fracture	L5	Bone Damage
Amputation	L6	Loss of body part