

Investigation Report - (Investigation UID - IR/TTK/AAA/25/00088)

Investigation Information

Investigation UID	IR/TTK/AAA/25/00088	Investigation Category	Fire & others investigation report
Investigation Status	Final Report Released	Created On	02-Dec-2025 04:36 PM
Approver Names	Lalit Aditya Kola, VAIBAHV VARUN, Shreya V		

Incident Information

Incident UID	IMF/TTK/COI/TIT/25/00124 Incident Category		Fire and others	
Site Name	Coimbatore Department Name		25 regression	
Process		Asset		
Incident Status	FinalReportReleased	eportReleased Created On		
Reported By	Lalit Aditya Kola			

Incident Description

"A small electrical fire broke out in the packaging area near Machine-3 due to overheating of a loose wire connection. Smoke was noticed by the operator and the area supervisor immediately initiated the emergency response. The fire was controlled within 3 minutes using a CO₂ extinguisher. No injuries were reported."

Sections

"A small electrical fire broke out in the packaging area near Machine-3 due to overheating of a loose wire connection. Smoke was noticed by the operator and the area supervisor immediately initiated the emergency response. The fire was controlled within 3 minutes using a CO ₂ extinguisher. No injuries were reported."
ec
e
9:
tive/New
ment: If Repetitive, Line:
till the System Issue / Failure):
i

Reviews and Learning

Documents revised based on CAPA: d	Lessons Learned: wc

Preventive Actions

UID	Site Name	Category Name	Created By	Description	Status
TA/TTK/COI/INR/25/00210	Coimbatore	Investigation Report	Lalit Aditya Kola		Drafted

Horizontal Deployment of Preventive Actions With in the Site

UID	Site Name	Category Name	Created By	Description	Status
TA/TTK/COI/INR/25/00211	Coimbatore	Investigation Report	Lalit Aditya Kola		Drafted

Horizontal Deployment of Preventive Actions Across the Sites

UID	Site Name	Category Name	Created By	Description	Status
TA/TTK/API/INR/25/00016	api site	Investigation Report	Lalit Aditya Kola		Drafted