

Investigation Report - (Investigation UID - IR/TTK/AAA/25/00061)

Investigation Information			
Investigation UID	IR/TTK/AAA/25/00061	Investigation Category	Fire & others investigation report
Investigation Status	Final Report Released	Created On	23-Oct-2025 06:50:36 PM
Approver Names	Bishal Mondal, Kumar Samarjeet, Lalit Aditya Kola		

Incident Information			
Incident UID	IMF/TTK/CO/TIT/25/00086	Incident Category	Fire and others
Site Name	Coimbatore	Department Name	25 regression
Incident Status	FinalReportReleased	Created On	23-Oct-2025 06:46:15 PM
Reported By	Mounika Laisetti		

Sections	
Is any Injury Occured	<div><input checked="" type="radio"/> Yes</div> <div><input type="radio"/> No</div>
Incident Description	A small fire broke out near the electrical control panel due to a short circuit caused by water seepage during heavy rain. The fire was quickly extinguished by the in-house emergency response team using a CO2 extinguisher.
Details of Loss/Property Damage	NA

Cost Estimate		
S.No	List of Damage Property	Value
1	Indirect Cause: Inadequate supervision and verification of PPE compliance before work.	NA

Occurence:- Repetitive/New		
If Repetitive, Last date of Incident: 28-Oct-2025	If Repetitive, Plant/Department: NA	If Repetitive, Line: NA

Root Cause Analysis (Why-Why: Drill down till the System Issue / Failure):		
S.No	Why	Root Cause:: NA
1	NA	

Reviews and Learning	
Documents revised based on CAPA: NA	Lessons Learned: NA

Preventive Actions					
UID	Site Name	Category Name	Created By	Description	Status
NA					

Horizontal Deployment of Preventive Actions With in the Site					
UID	Site Name	Category Name	Created By	Description	Status
NA					

Horizontal Deployment of Preventive Actions Across the Sites					
UID	Site Name	Category Name	Created By	Description	Status
NA					