

Incident Report - (Incident UID - IMF/TTK/COI/TIT/25/00043)

Incident Information

Incident UID	IMF/TTK/COI/TIT/25/00043	Category Name	Fire and others
Incident Description	Fire: During routine operations in the production area, a small fire broke out near the electrical panel due to a suspected short circuit. The fire was immediately detected by staff, and fire extinguishers were used to control the flames before spreading. No injuries were reported, but minor property damage occurred. Others: While performing housekeeping activities, an employee slipped on a wet floor due to water leakage from a nearby pipeline. The worker sustained minor injuries and was taken to the medical room for first aid. The leakage source was identified and isolated to prevent recurrence.	Status	FinalReportReleased
Site Name	Coimbatore	Department Name	Maintenance
Treatment of Injury	NA	Reported By	Sayan Mondal
Incident Date & Time	09-Sep-2025 12:00:00 AM	Created On	24-Sep-2025 07:57:47 PM

Sections

Photograph of the incident

Attach: 0

Immediate corrective steps taken

Actions: NA

Category of incident	<div><input checked="" type="radio"/> Fire <input type="radio"/> Flood <input type="radio"/> Cyclone <input type="radio"/> Heavy rain <input type="radio"/> Epidemic disease <input type="radio"/> Local threat</div>
----------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

FIR Team

Sequence	Name	Level of Approver
----------	------	-------------------

Injured Persons

NA