

Incident Report - (Incident UID - IMF/TTK/COI/IAP/25/00055)

Incident Information

Incident UID	IMF/TTK/COI/IAP/25/00055	Category Name	Injury-same as prod- don't delete
Incident Description	An operator touched a hot surface of a heat-sealing machine during preventive maintenance, resulting in a minor burn on the palm.	Status	FinalReportReleased
Site Name	Coimbatore	Department Name	Maintenance
Incident Date & Time	22-Oct-2025 12:00:00 AM	Created On	23-Oct-2025 05:28:40 PM
Reported By	Shreya V		

Sections

Level of Injury	<input type="radio"/> L1-Bruise <input checked="" type="radio"/> L2-Abrasion <input type="radio"/> L3-Burn <input type="radio"/> L4-Laceration <input type="radio"/> L5-Fracture <input type="radio"/> L6-Amputation
-----------------	---

Photograph of injury & machine

Attach: 3

Attachments


Injury treatment details

Number of people injured:: 1	Treatment of Injury: Treated at OHC & Referred for Diagnosis	Details of treatment given & doctor's advice:: First-aid ointment applied; referred to EHS-approved clinic for follow-up to rule out blister formation.
------------------------------	--	---

Injured person details

Name of the injured person: Deepa S.	Gender: Female	Role – ON / OFF: Off Roll	If Off role, mention the contractor name: : R.K. Facility Services
Age: 32	No. of Year's total experience in TTK Prestige : 1 year	No. of years in this process / machine : 6	Injury Happened in Which Shift? : B shift

Attachments



[ev1_2025-10-23_11-58-40-5840_f87fab8-42d2-440c-87c5-805aa1638627.mp4](#)

[camerasaissue_2025-10-23_11-58-40-5840_e5bb36ef-5913-472e-b9b7-4fa70dc13676.mp4](#)

[OQSHA_IMS System 2025-10-13_19-37-26-3726_2025-10-23_11-58-40-5840_b6d3ca61-85d8-495f-8075-201f3ef82f99.csv](#)

Definition:

Injury Type	Level	Definition
Bruise	L1	Blood Clot
Abrasion	L2	Skin Rubbed with Rough Surface
Burn	L3	Skin Burn due to fire, chemical, etc
Laceration	L4	Tear or a cut in the skin
Fracture	L5	Bone Damage
Amputation	L6	Loss of body part