

Investigation Report - (Investigation UID - IR/TTK/FSI/25/00004)

Investigation Information

Investigation UID	IR/TTK/FSI/25/00004	Investigation Category	First-Aid Safety Incident Investigation Report
Investigation Status	Final Report Released	Created On	27-Nov-2025 04:44:02 PM
Approver Names	Krystin Cope, Mozell Heaton, Kalvin Tran, Maiya Walden		

Incident Information

Incident UID	IMF/TTK/HOS/INJ/25/00011	Incident Category	Injury
Site Name	Mathiston	Department Name	Production
Process	Press shop operation	Asset	Hydraulic H Frame Press
Incident Status	FinalReportReleased	Created On	22-Nov-2025 10:21:49 PM
Reported By	Ashby Graham		

Incident Description

While loading & unloading of SS cooker body in hydraulic press, the injured person finger caught in-between the two cooker body & minor laceration observed in the left-hand middle finger. The employee was wearing proper PPE at the time of the incident & No bleeding, No Swelling and No bone injury. At site investigation, it was found that, Hydraulic press ram came down unexpectedly because of machine malfunction.

Sections

Category of Incident	<input type="radio"/> Category 5 - First Aid at OHC <input type="radio"/> Category 2 - Permanent disablements-Reportable <input type="radio"/> Category 3 - Partial disablements-Reportable <input type="radio"/> Category 4 - Injury taken to outside hospital - Non reportable <input checked="" type="radio"/> Category 5 - First Aid at OHC
Findings	Cotton knotted blue gloves was used with rubber gloves on top of it. Body placed one on another Main Ram is moving downward from top after completing one the cycle
Immediate Action Taken	The body loading and unloading carrying out separately.
Root Cause	Ram is moving downward after completing the cycle
Photographs	0
Level of Injury	<input type="radio"/> L1-Bruise <input type="radio"/> L2-Abrasion <input type="radio"/> L3-Burn <input checked="" type="radio"/> L4-Laceration <input type="radio"/> L5-Fracture <input type="radio"/> L6-Amputation

Report Prepared by

Name: Hyder Khadi Saab	Date: 27-Nov-2025
-------------------------------	--------------------------

Preventive Actions

UID	Site Name	Category Name	Assignee Name	Due Date	Created By	Description	Status
NA							

Horizontal Deployment of Preventive Actions With in the Site

UID	Site Name	Category Name	Assignee Name	Due Date	Created By	Description	Status
-----	-----------	---------------	---------------	----------	------------	-------------	--------

AT/TTK//INR/25/00013	Mathiston	Investigation Report	Zora Hamlet	08-Dec-2025 04:30:00 PM	Kalvin Tran	EP-4 Hydraulic Main Ram must remain in the home position when in idle condition.	Closed
AT/TTK//INR/25/00014	Mathiston	Investigation Report	Debbi McClintock	06-Dec-2025 10:00:00 PM	Kalvin Tran	Hydraulic Press monthly inspection checklist must be displayed and monitored.	Closed

Horizontal Deployment of Preventive Actions Across the Sites

UID	Site Name	Category Name	Assignee Name	Due Date	Created By	Description	Status
NA							

Injured person details

Name of the injured person: Akash Mirdha	Gender: Male	Role – ON / OFF: NA	If Off role, mention the contractor name: : Off role Worker
Age: Age - 27	No. of Year's total experience in TTK Prestige : 1	No. of years in this process / machine : 1	Injury Happened in Which Shift?: Shift - Second Shift