

Safety Alert Report

Organisation	Kura Oncology Inc.
Safety Alert UID	T/TRS/UCC/26/00037
Status	Open
DueDate	24-Mar-2026
Severity	Major
Site	Hickory Grove
Area	Medium Shop
User Type	Contractor
Company Name	Gossamer Bio Inc.
Person Name	Tahj Mccourt
Department	Production
Reported By	Jakayla Pizano
Mobile Number	+91 2000009218
Others Involved	NA
Category	Unsafe Condition
Description	<p>During the site visit BAY - D, it was observed that the BCFC underframe manipulators are in an unsafe condition. For locking the underframe, two interlocks should be provided on each side; however, only one interlocking is provided on both sides, which is inadequate. At the trunnion pin location, there is a provision for 4 bolts, but only 3 bolts have been installed. High risk of underframe slippage or movement, Equipment instability due to insufficient interlocking. Risk of mechanical failure at trunnion pin, Potential for serious injury, fatality, or equipment damage</p>
Safety Alert Image(s)	NA
Safety Alert Video(s)	NA
Safety Alert Audio(s)	NA
Safety Alert File(s)	NA
Created	21-Mar-2026 11:11:32 AM
Modified	21-Mar-2026 11:11:32 AM
Investigation Checklist	NA
Assigned To	Ammie Hammett
Resolved On	NA

Safety Alert History

21-Mar-2026 11:11:32 AM - Jakayla Pizano: A new record was created: Uid set to 'T/TRS/UCC/26/00037' Site set to 'Bharatpur' Reported By set to 'Narendra singh' Category set to 'Unsafe Condition' Department set to 'Production' Assigned To set to 'Subhash kumar' Severity set to 'Major' Due Date set to '24-Mar-2026' Area set to 'Medium Shop'

To view all Audio(s)/Video(s)/Photo(s)/File(s), Visit:

<https://www.incidentreporter365.com/#/incidents/view/258/68844>

This is a computer generated report. For queries please mail to contact@oqsha.com