

Pliant Therapeutics Inc.

Work Permit Report - (Work Permit UID - WP/PLRX/MAR/HWI/26/00001)

Work Permit Information

Work Permit UID	WP/PLRX/MAR/HWI/26/00001	Category Name	Hot work issue
Description		Status	Submit
Site Name	Keswick	Department Name	Default
Location		Initiated By	Lucky Eaton
Start Date & Time	08-Apr-2026 12:18:00 PM	End Date & Time	08-Apr-2026 06:00:00 PM
Created On	08-Apr-2026 12:23:35 PM	Due Date	08-Apr-2026 12:00:00 AM
Contractor	NA	Shift	NA

Sections

Reminder: Reminder:- Permit valid for 1 day (i.e., date of issued day and valid till 6.00pm only in any calendar day)	Work Description: NA	Work Location: NA	Have Execution agency carried out JSA?: NA
Has tool box talk conducted ?: No			

Person Working on the job

Name of Person Involved	Sign
NA	NA
NA	NA

TBT Conducted by: NA

Declaration by Requester - All Person deployed are competent for the job to be executed : NA

Attachments

No images available

[jsonformatter_7_2026-04-08_06-53-34-5334_efa88ace-5e5e-439e-beb6-08942c974e7c.txt](#)

PPEs and Equipment Required

<input type="checkbox"/> Safety Shoes	<input type="checkbox"/> Safety Helmet	<input type="checkbox"/> Hand Gloves	<input type="checkbox"/> Goggles/Shield
<input type="checkbox"/> Ear Plug/Muff			

General Precautions

1. Ensure Presence of Fire extinguisher.: Yes	2. Keep tight connections between the regulator and the cylinder(Gas cutting): Yes	3. Use IS Approved fittings (Flash back arrestor / Pressure regulators / Cutting torch etc.(Gas cutting): Yes	4. Regulators, pressure gauges and torches are undamaged and in sound working conditions (Gas cutting): Yes
5. All pressure gauges in working condition (Gas cutting): Yes	6. ELCB / RCCB must be installed in welding machines.: Yes	7. Ensure Adequate ventilation, use exhaust if required (Welding).: Yes	8. Ensure earthing of welding machine for proper electrical continuity.: Yes
9. Ensure no combustible exposed to possible ignition with in 11 Mtr: Yes	10. No lose wirings / broken cables.: Yes	11. Ensure Wheel-guard fitted in grinding machine (Grinding Safety).: Yes	12. Wheel RPM shall be greater that machine RPM (Grinding Safety).: Yes
13. Check validity of wheel (Expired wheel must not be used) - (Grinding Safety).: Yes	14. Contactors should take care of barricading their respective work places.: Yes	15. Required PPE's should be worn at all the time during the work (As mentioned in work permit): Yes	16. In case you hear Emergency siren, go to your nearest safe assembly point.: Yes
17. Check all the Equipment / Tools are in good condition (Duly Inspected before work execution): Yes	18. Place hazard Sign board in place (If Required).: Yes		

Additional Remarks

Additional Remarks : NA

Periodic Inspection after signing the permit

Time	Remarks	Sign
NA	NA	NA
NA	NA	NA

Fire Watcher

Fire Watcher Name	Remarks	Remarks	One hour present - To Time	One hour present - From Time	Sign of Fire Watcher	Three Hour Intermittently to Time	Three Hour Intermittently from Time	Sign of Fire Watcher
NA	NA	NA	NA	{ "Labels": "Sign of Fire Watcher", "Declaration": "", "SignedUserId": 0, "SignedUserName": "", "SignedMobileNumber": "", "SignedDateAndTime": "", "SignedAcroleid": 0, "DepartmentId": null, "IsAssignedToMandatory": false, "InspectionStatusId": 0, "InspectionStatusName": "", "IsRejected": false }	NA	NA	NA	NA

Approvers

{ApproversDetails}

History

Created On	Created By	Comment	Attachments
08-Apr-2026 12:23:35 PM	Lucky Eaton	A new record was created: Site Name set to 'Keswick' Department set to 'Default' Type Of Permit set to 'Hot work issue' Name Of Requestor set to 'Lucky Eaton' Work Permit Date Start set to '08-Apr-2026' Work Permit Date End set to '08-Apr-2026' Work Permit Time Start set to '12:18 PM' Work Permit Time End set to '06:00 PM' Is Manual Ptw set to 'False' Status set to 'Submit'	NA