

Pliant Therapeutics Inc.

Work Permit Report - (Work Permit UID - WP/PLRX/MAR/HWW/26/00002)

Work Permit Information

Work Permit UID	WP/PLRX/MAR/HWW/26/00002	Category Name	Hot Work
Description		Status	Approve
Site Name	Keswick	Department Name	Default
Location		Initiated By	Lucky Eaton
Start Date & Time	07-Apr-2026 04:32:00 PM	End Date & Time	07-Apr-2026 06:00:00 PM
Created On	07-Apr-2026 03:33:19 PM	Due Date	07-Apr-2026 12:00:00 AM
Contractor	NA	Shift	NA

Sections

Reminder: Reminder:- Permit valid for 1 day (i.e., date of issued day and valid till 6.00pm only in any calendar day)	Work Description: NA	Work Location: NA	Have Execution agency carried out JSA?: NA
Has tool box talk conducted ?: NA			

Person Working on the job

Name of Person Involved	Sign
NA	NA

TBT Conducted by: NA	Declaration by Requester - All Person deployed are competent for the job to be executed : NA
-----------------------------	---

PPEs and Equipment Required

<input type="checkbox"/> Safety Shoes	<input type="checkbox"/> Safety Helmet	<input type="checkbox"/> Hand Gloves	<input type="checkbox"/> Goggles/Shield
<input type="checkbox"/> Ear Plug/Muff			

General Precautions

1. Ensure Presence of Fire extinguisher.: NA	2. Keep tight connections between the regulator and the cylinder(Gas cutting): NA	3. Use IS Approved fittings (Flash back arrestor / Pressure regulators / Cutting torch etc.(Gas cutting): NA	4. Regulators, pressure gauges and torches are undamaged and in sound working conditions (Gas cutting): NA
5. All pressure gauges in working condition (Gas cutting): NA	6. ELCB / RCCB must be installed in welding machines.: NA	7. Ensure Adequate ventilation, use exhaust if required (Welding).: 0	8. Ensure earthing of welding machine for proper electrical continuity.: NA
9. Ensure no combustible exposed to possible ignition with in 11 Mtr: Yes	10. No lose wirings / broken cables.: Yes	11. Ensure Wheel-guard fitted in grinding machine (Grinding Safety).: Yes	12. Wheel RPM shall be greater that machine RPM (Grinding Safety).: Yes
13. Check validity of wheel (Expired wheel must not be used) - (Grinding Safety).: Yes	14. Contactors should take care of barricading their respective work places.: Yes	15. Required PPE's should be worn at all the time during the work (As mentioned in work permit): Yes	16. In case you hear Emergency siren, go to your nearest safe assembly point.: Yes
17. Check all the Equipment / Tools are in good condition (Duly Inspected before work execution): Yes	18. Place hazard Sign board in place (If Required).: Yes		

Additional Remarks

Additional Remarks : NA

Periodic Inspection after signing the permit

Time	Sign
NA	NA

Fire Watcher

Fire Watcher Name: NA	One hour present - To Time: 06:30:00 PM	One hour present - From Time: 06:30:00 PM	Sign of Fire Watcher : NA
Three Hour Intermittently to Time: 06:30:00 PM	Three Hour Intermittently from Time: 06:30:00 PM	Sign of Fire Watcher: NA	

Permit close out - Issuer to close out, Execution agency to return permit to issuing authority

<input type="checkbox"/> I have Inspect the work area and confirmed that work has been completed, Informed to concerned stakeholder	<input type="checkbox"/> Ensure no post hazards (Incl Housekeeping) after completion of work.	Name and Signature of Issuer: NA
---	---	----------------------------------

Approvers

{ApproversDetails}

History

Created On	Created By	Comment	Attachments
07-Apr-2026 03:34:07 PM	Lucky Eaton	Status has been updated to Approved Approve	NA
07-Apr-2026 03:33:56 PM	Lucky Eaton	Approve	NA
07-Apr-2026 03:33:45 PM	Lucky Eaton	Status has been updated to Partially Approved Approve	NA
07-Apr-2026 03:33:33 PM	Lucky Eaton	Status has been updated to Submitted	NA
07-Apr-2026 03:33:19 PM	Lucky Eaton	A new record was created: Site Name set to 'Keswick' Department set to 'Default' Type Of Permit set to 'Hot Work' Name Of Requestor set to 'Lucky Eaton' Work Permit Date Start set to '07-Apr-2026' Work Permit Date End set to '07-Apr-2026' Work Permit Time Start set to '04:32 PM' Work Permit Time End set to '06:00 PM' Is Manual Ptw set to 'False' Status set to 'Draft'	NA