

# Pliant Therapeutics Inc.

## Work Permit Report - (Work Permit UID - WP/PLRX/MAR/HWW/26/00003)

### Work Permit Information

Work Permit UID	WP/PLRX/MAR/HWW/26/00003	Category Name	Hot Work
Description		Status	PartiallyApprove
Site Name	Keswick	Department Name	Default
Location		Initiated By	Lucky Eaton
Start Date & Time	07-Apr-2026 03:36:00 PM	End Date & Time	07-Apr-2026 06:00:00 PM
Created On	07-Apr-2026 03:36:42 PM	Due Date	07-Apr-2026 12:00:00 AM
Contractor	NA	Shift	NA

### Sections

<b>Reminder:</b> Reminder:- Permit valid for 1 day (i.e., date of issued day and valid till 6.00pm only in any calendar day )	<b>Work Description:</b>	<b>Work Location:</b>	<b>Have Execution agency carried out JSA?:</b>
<b>Has tool box talk conducted ?:</b>			

Person Working on the job

<b>Name of Person Involved</b>	<b>Sign</b>
NA	NA

<b>TBT Conducted by:</b>	<b>Declaration by Requester - All Person deployed are competent for the job to be executed :</b>
--------------------------	--

PPEs and Equipment Required

<input type="checkbox"/> Safety Shoes	<input type="checkbox"/> Safety Helmet	<input type="checkbox"/> Hand Gloves	<input type="checkbox"/> Goggles/Shield
<input type="checkbox"/> Ear Plug/Muff			

General Precautions

<b>1. Ensure Presence of Fire extinguisher.:</b>	<b>2. Keep tight connections between the regulator and the cylinder(Gas cutting):</b>	<b>3. Use IS Approved fittings (Flash back arrestor / Pressure regulators / Cutting torch etc.(Gas cutting):</b>	<b>4. Regulators, pressure gauges and torches are undamaged and in sound working conditions (Gas cutting):</b>
<b>5. All pressure gauges in working condition (Gas cutting):</b>	<b>6. ELCB / RCCB must be installed in welding machines.:</b>	<b>7. Ensure Adequate ventilation, use exhaust if required (Welding).: 0</b>	<b>8. Ensure earthing of welding machine for proper electrical continuity.: 1</b>
<b>9. Ensure no combustible exposed to possible ignition with in 11 Mtr: 1</b>	<b>10. No lose wirings / broken cables.:</b> 1	<b>11. Ensure Wheel-guard fitted in grinding machine (Grinding Safety).: 1</b>	<b>12. Wheel RPM shall be greater that machine RPM (Grinding Safety).: 1</b>
<b>13. Check validity of wheel (Expired wheel must not be used ) - (Grinding Safety).: 1</b>	<b>14. Contactors should take care of barricading their respective work places.: 1</b>	<b>15. Required PPE's should be worn at all the time during the work (As mentioned in work permit): 1</b>	<b>16. In case you hear Emergency siren, go to your nearest safe assembly point.: 1</b>
<b>17. Check all the Equipment / Tools are in good condition (Duly Inspected before work execution): 1</b>	<b>18. Place hazard Sign board in place (If Required).: 1</b>		

Additional Remarks

<b>Additional Remarks :</b>
-----------------------------

Periodic Inspection after signing the permit

<b>Time</b>	<b>Sign</b>
NA	Signed by Lucky Eaton at 08-Apr-2026 07:48

Fire Watcher						
<b>Fire Watcher Name</b>	<b>One hour present - To Time</b>	<b>One hour present - From Time</b>	<b>Sign of Fire Watcher</b>	<b>Three Hour Intermittently to Time</b>	<b>Three Hour Intermittently from Time</b>	<b>Sign of Fire Watcher</b>
NA	NA	NA	Signed by Lucky Eaton at 08-Apr-2026 07:48	NA	NA	NA

Permit close out - Issuer to close out, Execution agency to return permit to issuing authority		
<input type="checkbox"/> I have Inspect the work area and confirmed that work has been completed, Informed to concerned stakeholder	<input type="checkbox"/> Ensure no post hazards (Incl Housekeeping) after completion of work.	Name and Signature of Issuer: NA

**Approvers**

{ApproversDetails}

**History**

Created On	Created By	Comment	Attachments
08-Apr-2026 01:18:17 PM	Lucky Eaton	Status has been updated to Partially Approved Sign	NA
07-Apr-2026 03:37:23 PM	Lucky Eaton	Status has been updated to Approved Approve	NA
07-Apr-2026 03:37:15 PM	Lucky Eaton	Approve	NA
07-Apr-2026 03:37:05 PM	Lucky Eaton	Status has been updated to Partially Approved Approve	NA
07-Apr-2026 03:36:47 PM	Lucky Eaton	Status has been updated to Submitted	NA
07-Apr-2026 03:36:42 PM	Lucky Eaton	A new record was created: Site Name set to 'Keswick' Department set to 'Default' Type Of Permit set to 'Hot Work' Name Of Requestor set to 'Lucky Eaton' Work Permit Date Start set to '07-Apr-2026' Work Permit Date End set to '07-Apr-2026' Work Permit Time Start set to '03:36 PM' Work Permit Time End set to '06:00 PM' Is Manual PtW set to 'False' Status set to 'Draft'	NA