

Work Permit Report - (Work Permit UID - WP/TTK/COI/CWP/25/00007)

Work Permit Information

Work Permit UID	WP/TTK/COI/CWP/25/00007	Category Name	General - Cold Work
Description		Status	Close
Site Name	Washoe Valley	Department Name	Assembly
Location		Initiated By	Hebert Eaton
Start Date & Time	23-Sep-2025 01:30:00 PM	End Date & Time	23-Sep-2025 07:30:00 PM
Created On	23-Sep-2025 12:32:06 PM	Due Date	23-Sep-2025 12:00:00 AM
Contractor	NA	Shift	NA

Sections

1. Hazards Identified			
<input type="checkbox"/> Presence of Toxic Gas Fumes	<input type="checkbox"/> Presence of Flammable Gas Fumes	<input type="checkbox"/> Work on Standing Ladder	<input type="checkbox"/> Work on Scaffolding
<input type="checkbox"/> Slip Hazard	<input type="checkbox"/> Improper Access to reach confined space work area	<input type="checkbox"/> Lack of Oxygen Level	<input type="checkbox"/> Unguarded Opening
<input type="checkbox"/> No access ladder inside the confined space	<input type="checkbox"/> Poor Lighting	<input type="checkbox"/> Work near sharp edges in vessel inside	<input type="checkbox"/> Height Work (Above 1.5 Mtr.)
<input type="checkbox"/> Mechanical / Electrical Sparks	<input type="checkbox"/> Sharp Edges	<input type="checkbox"/> Trip Hazard	<input type="checkbox"/> Noise / Vibration
<input type="checkbox"/> Excavation Collapse	<input type="checkbox"/> Steam	<input type="checkbox"/> Work near Over Head Electrical Line	<input type="checkbox"/> Static Electricity
<input type="checkbox"/> Work on Running Vessel / Tank	<input type="checkbox"/> Oil Spillage Observed	<input type="checkbox"/> Pressurized Line	Other Hazards::

2. Control Measures			
YES	NO	NA	Check Points for the Initiator
			Is all hand tools & equipment's inspected & tag provided?
			Area is free from any Loose electrical joint/cables & sharp edges.
			Ensure no underground cables & pipelines in vicinity of work area.
			Ensure no unguarded openings
			Surrounding area is checked, cleaned & safe
			Equipment properly drained / de pressurized
			LOTO to applied for the work & equipment is safe
			Availability of sufficient illumination at work spot. Checked relevant PPE.
			People are competent to do the work
			Any other source of potential hazard if any remove before start of work.
			All necessary guarding provided in the rotary objects
			Safety devices are not bypassed
			Ensure the work not carrying in running operation
			Caution board mentioning "Job in Progress" installed near working area.
			If any of the above criteria required is not met, then do not issue the work permit

3. Safety Equipment Requirement & PPE to be used

<input type="checkbox"/> Safety Glasses	<input type="checkbox"/> Hand Gloves	<input type="checkbox"/> Face Shield / Welding Goggle	<input type="checkbox"/> Apron
<input type="checkbox"/> Nose Mask / Respirators	<input type="checkbox"/> Ear Plug / Muff	<input type="checkbox"/> Helmet	<input type="checkbox"/> Warning Signs
<input type="checkbox"/> Safety Harness / Lifeline	<input type="checkbox"/> Scaffolds & Ladders	<input type="checkbox"/> Forced Ventilation	<input type="checkbox"/> Safety Shoes
<input type="checkbox"/> Fire Extinguisher No.	<input type="checkbox"/> Locks / Tags	<input type="checkbox"/> Barricades	Any other ::
LOTO Tag Reference No.:			

Approvers

{ApproversDetails}

History

Created On	Created By	Comment	Attachments
23-Sep-2025 01:07:55 PM	Hebert Eaton	Status has been updated to Closed	NA
23-Sep-2025 01:01:29 PM	Hebert Eaton	Status has been updated to Approved	NA
23-Sep-2025 01:01:29 PM	Hebert Eaton	Approved	NA
23-Sep-2025 12:32:06 PM	Hebert Eaton	A new record was created: Uid set to 'WP/TTK/COI/CWP/25/00007' Category Name set to 'General - Cold Work' Work Permit Status Name set to 'Submit'	NA