

Incident Report - (Incident UID - IMF/TTK/COI/TIT/25/00124)

Incident Information

Incident UID	IMF/TTK/COI/TIT/25/00124	Category Name	Fire and others
Status	FinalReportReleased	Site Name	Coimbatore
Department Nam e	25 regression	Incident Date & T ime	09-Sep-2025 12:00:00 AM
Created On	02-Dec-2025 04:15:14 PM	Reported By	Lalit Aditya Kola

Incident Description

"A small electrical fire broke out in the packaging area near Machine-3 due to overheating of a loose wire connection. Smoke was noticed by the operator and the area supervisor immediately initiated the emergency response. The fire was controlled within 3 minutes using a C O₂ extinguisher. No injuries were reported."

Sections

Category of incident	Fire
	○ Flood
	C Cyclone
	C Heavy rain
	C Epidemic disease
	C Local threat

Photograph of the incident

۸	tta	•	h		•
м	LLi	16	п	١.	_

Personiche Angaben	Initiativbewerbung Zentrale Wien
1	11013
Verschau	
	Anschreiben
	max. 1 Arhang (PDP, doc. docx, jog, proj., max. 5 MB
	Dateien hierher ziehen oder Dateien auswählen

OQSHA_MOC_2025-12-02_15-25-19-2519_2025-12-02_10-45-14-4514_4c630d37-50ef-49b9-8d6d-a137de01fff8.csv

Immediate corrective steps taken

Actions	Responsibility	Status	Completion date
Disconnected power to Machine- 3 and inspected wirin	EHS Head	WIP	2025-12-31
Action 2	edc	fvs	NA

Investigation Team

Name	
Sayan Mondal	

Incident History

Created On	Updated By	Comment	Attachments
02-Dec-2025 0 4:36:35 PM	Lalit Aditya Kola	User Name has been updated to 'Sayan Mondal'	
02-Dec-2025 0 4:28:56 PM	VAIBAHV VARUN	Incident Status has been updated to 'FIRReleased'	
02-Dec-2025 0 4:27:58 PM	Lalit Aditya Kola	Incident Status has been updated to 'Validated'	
02-Dec-2025 0 4:17:53 PM	Lalit Aditya Kola	Incident Status has been updated to 'Submit'	

	02-Dec-2025 0 4:15:15 PM	Lalit Aditya Kola	A new record was created: Incident Description set to ""A small electrical fir e broke out in the packaging area near Machine-3 due to overheating of a loose wire connection. Smoke was noticed by the operator and the area su pervisor immediately initiated the emergency response. The fire was contro lled within 3 minutes using a CO2 extinguisher. No injuries were reported." Site Name set to 'Coimbatore' Category Name set to 'Fire and others' Department Name set to '25 regression' Status set to 'Draft' Incident Date Time s et to '09-Sep-2025 12:00:00 AM'		
--	-----------------------------	-------------------	--	--	--

Definition:

Injury Type	Level	Definition
Bruise	L1	Blood Clot
Abrasion	L2	Skin Rubbed with Rough Surface
Burn	L3	Skin Burn due to fire, chemical, etc
Laceration	L4	Tear or a cut in the skin
Fracture	L5	Bone Damage
Amputation	L6	Loss of body part