

Incident Report - (Incident UID - IMF/TTK/COI/IAP/25/00040)

Incident Information

Incident UID	IMF/TTK/COI/IAP/25/00040	Category Name	Injury-same as prod- don't delete
Incident Description	An operator touched a hot surface of a heat-sealing machine during preventive maintenance, resulting in a minor burn on the palm.	Status	FinalReportReleased
Site Name	Coimbatore	Department Name	Maintenance
Incident Date & Time	07-Oct-2025 04:00:00 AM	Created On	10-Oct-2025 10:06:14 AM
Reported By	Lalit Aditya Kola		

Sections

Level of Injury	<input type="radio"/> L1-Bruise <input type="radio"/> L2-Abrasion <input checked="" type="radio"/> L3-Burn <input type="radio"/> L4-Laceration <input type="radio"/> L5-Fracture <input type="radio"/> L6-Amputation
------------------------	---

Photograph of injury & machine

Attach: 1

Attachments



Injury treatment details

Number of people injured:: 1	Treatment of Injury: Treated at OHC & Referred for Diagnosis	Details of treatment given & doctor's advice:: First-aid ointment applied; referred to EHS-approved clinic for follow-up to rule out blister formation.
-------------------------------------	---	--

Injured person details

Name of the injured person: Deepa S.	Gender: Female	Role – ON / OFF: Off Roll	If Off role, mention the contractor name: : R.K. Facility Services
Age: 32	No. of Year's total experience in TTK Prestige : 1 year	No. of years in this process / machine : 6 months	Injury Happened in Which Shift? : B Shift

Attachments

