



Doc No: MHCPL-EHS-PTW-07

The Main Isolation Switch location is known to All Shock Treatment chart is available and is understood through TBT.: **No**

Permit To Work Report - Hot Work (Permit UID - APA/APA/ABCCON/HW/0002)

		formation	
Type of permit	Name of project/site	Contractor company	Name of client/contractor
Hot Work	Aparna Sarovar	Abc Constructions	Raj Kumar Pativada
	Work Inf	formation	
Start date / Close Date	2/26/2025 12:00:00 AM / 2/27/2025 12:00:00 AM	Work location	
Start time / End time	2/27/2025 4:14:00 PM / 2/27/2025 5:00:00 PM	Reference permit no.	
No. of workers	0	Tools/ equipment to be used	
Scope of work			
Description of work			
	Sec	tions	
	Haz	ards	
Electrical Shock	Carbon Fumes	Arc Flash	Burns 🗖
Fire /Explosion	Person Fall	Equipment Fall	Other Hazards:
	Precaution	ons Taken	
Isolation	LOTO Applied □	Isolation Switch Available	Cordoned Area
HIRA Undertaken	Signage's Provided	SOP	Grounding Provided
ELCB / RCCB Provided	Awareness on expected emergencies ?	Other Precautions::	<u> </u>
	Toolbo	ox Talks	-
Topics discussed:		Attach photo: 0	
	Job Spe	cific PPEs	
Safety Helmet □	Safety Shoes	Full Body Harness	Cover All
Welding Face Shield ☐	Leather Hand Gloves	Leather Apron	UV Protection Shield
Other PPE's:			
	- Safety Con	siderations	
Has the area at the work location been cleared of all the combustible materials & any other lubricants etc?: No	Has a flashback arrestor at both sides (cylinder & torch) been provided to the gas-cutting set?: No	Have Suitable Fire Extinguishers/sand buckets been kept handy at the work site?: No	Have Welding Screen (Yellow) wet gunny bag/fire blanket beel used to protect against sparks?
Vertical clearance. (at least 2 meters above the platform) (Supervision should be provided if sufficient clearance is not available): No	Is barricading being provided below while doing work at height?: No	Is the gas-cutting cylinder checked for any leakages?: No	Are the gas cylinders secured i a trolley using chains?: No
Do all workers involved in hot work have proper training on safety procedures and equipment use?: No	Do welding machines have ELCB/RCCB and proper earthing?: No	Availability and use of PPEs. (Mandatory PPE + Leather Apron, Welding Face Shield, Leather Hand Gloves): No	Use of Full body harness with double lanyard & lifeline or anchor point.(while doing hot work at height): No
Any other requirement (If Yes, please specify): Emergency exits are available, and Emergency vehicle and First-aid providers shall be assured during the work The Main Isolation Switch			

Approval and authorization

Requestor_Trial-1	Issuer_Trial-2	Approver_Trial-3	Reviewer_Trial-4
Name: Raj Kumar Pativada	Name: Lalit Issuer	Name: Harsha THD	Name: Sayan Requester
Phone: +919160948627	Phone: +917993748764	Phone: +918555849483	Phone: +919898989898
Requested On: 25-Feb-2025	Issued On: 25-Feb-2025	Approved On: 25-Feb-2025	Reviewed On: 25-Feb-2025
08:15:00 PM	11:10:14 PM	11:12:14 PM	11:14:19 PM

Extension UID: HZNIE2

	Conditions
-vto neion	CANditions

Requested	Issued	Approved	Reviewed
Name: Raj Kumar Pativada Mobile: +919160948627 Requested On: 26-Feb-2025 04:34:06 PM Duration: 1 hour(s)	Name: Mobile: Issued On: NA Duration: NA hour(s)	Name: Mobile: Approved On: NA Duration: NA hour(s)	Name: Mobile: Reviewed On: NA Duration: NA hour(s)

Permit To Work Closure

Check 1 □	Check 2: NA	Check 4: No	Check 6 □
Check 7: 0			
Check 3:	Check 5:		

Permit To Work History

Created On	Created By	Comment	Attachments
26-Feb-2025 09:49:04 PM	System User	The status has changed to Temporarily_Suspended automatically.	
26-Feb-2025 09:46:40 PM	Raj Kumar Pativada	Status changed to Validation Requested -14. No changes were made. Assigned Issuer: Lalit Issuer	
26-Feb-2025 05:01:05 PM	System User	The status has changed to Temporarily_Suspended automatically.	
26-Feb-2025 04:34:06 PM	Raj Kumar Pativada	The status has changed to Extension Requested -9. Assigned Issuer: Lalit Issuer Duration: 1 hour(s).	
25-Feb-2025 11:14:19 PM	Sayan Requester	The status has changed to Reviewed -4.	
25-Feb-2025 11:12:14 PM	Harsha THD	The status has changed to Approved -1. Assigned Reviewer: Sayan Requester	
25-Feb-2025 11:10:14 PM	Lalit Issuer	The status has changed to Issued -2. Assigned Approver: Harsha THD	
25-Feb-2025 08:15:00 PM	Raj Kumar Pativada	The status has changed to Requested -3. Assigned Issuer: Lalit Issuer	