

Work Permit Report - (Work Permit UID - WP/FBYDW/COI/HOW/26/00001)

Work Permit Information

Work Permit UID	WP/FBYDW/COI/HOW/26/00001	Category Name	Hot Work
Description	7 Spindle Main Panel board cutting work for Buzzer	Status	Submit
Site Name	Washoe Valley	Department Name	Maintenance
Location	Polishing	Initiated By	Curley Benedict
Start Date & Time	27-Mar-2026 02:00:00 PM	End Date & Time	27-Mar-2026 10:00:00 PM
Created On	26-Mar-2026 06:42:56 PM	Due Date	27-Mar-2026 12:00:00 AM
Contractor	NA	Shift	NA

Sections

1. Hazards Identified			
<input type="checkbox"/> Presence of Toxic Gas Fumes	<input type="checkbox"/> Sharp Edges	<input type="checkbox"/> Poor Lighting	<input type="checkbox"/> Combustible Materials Nearby
<input type="checkbox"/> Work near Over Head Electrical Line	<input type="checkbox"/> Presence of Flammable Gas	<input type="checkbox"/> Tripp Hazard	<input type="checkbox"/> Static Electricity
<input checked="" type="checkbox"/> Flammable Materials Nearby	<input type="checkbox"/> Improper Access	<input type="checkbox"/> Unguarded Opening	<input type="checkbox"/> Slip Hazard
<input type="checkbox"/> Steam	<input type="checkbox"/> Oil Spillage Observed	<input type="checkbox"/> Moving / Running Machinery	<input type="checkbox"/> Confined Space
<input type="checkbox"/> Excavation Collapse	<input type="checkbox"/> Vibration	<input type="checkbox"/> Height Work	<input type="checkbox"/> Work on Fragile Roofs
<input type="checkbox"/> Mechanical / Electrical Spark	<input type="checkbox"/> Noise	<input type="checkbox"/> Pressurized Line	Other Hazard(s):
2. Control Measures			

Name.....: M. Nandhakumar	If any of the above criteria required is not met, then do not issue the work permit.:
---------------------------	---

YES	NO	NA	Check Points for the Initiator
✓			Has the equipment mechanically locked to avoid rotation?
✓			Has the insulation of electrical equipment been checked before the work start?
✓			Have all the hand tools inspected & green tag provided?
✓			Have all flammable or combustible material been removed from work site (at least 3 meters away)?
✓			Has proper ventilation & lighting provided?
✓			Is Fire blanket required & provided?
✓			Is fire hydrant & fire water pump system in operation
✓			Is a fire extinguisher available and ready?
✓			Is gas monitoring carrying for hot work carrying in flammable storage area?
✓			Has a fire watch person been assigned while performing hot work? Name.....
✓			If sparks fall to lower levels, has adequate protection been provided?
✓			Has the work and adjacent areas been isolated with warning tapes and barricades.
✓			Flashback arrestor provided on nozzle torch as well as on cylinder regulator
✓			Monitor the Hot work area after completing of the work for 1 Hr
✓			Is the people planned for hot work is well experience & trained
✓			Is general safety induction given to the people working in hot work area
✓			Is the adequate PPEs listed in Section 3 is available with the work crew

3. Safety Equipment Requirement & PPE to be used

<input checked="" type="checkbox"/> Safety Glasses	<input type="checkbox"/> Nose Mask / Respirators	<input type="checkbox"/> Safety Harness / Lifeline	<input checked="" type="checkbox"/> Fire Extinguisher No.
<input checked="" type="checkbox"/> Safety Shoes	<input checked="" type="checkbox"/> Hand Gloves	<input type="checkbox"/> Ear Plug/ Muff	<input type="checkbox"/> Scaffolds & Ladders
<input type="checkbox"/> LOTO	<input type="checkbox"/> Barricades & Warning Signs	<input checked="" type="checkbox"/> Face Shield / Welding Goggle	<input type="checkbox"/> Helmet
<input type="checkbox"/> Forced Ventilation	<input type="checkbox"/> Apron	<input type="checkbox"/> Any Other:	LOTO Tag Reference No.:

Approvers

{ApproversDetails}

History

Created On	Created By	Comment	Attachments
26-Mar-2026 06:42:57 PM	Curley Benedict	A new record was created: Site Name set to 'Washoe Valley' Department set to 'Maintenance' Department Incharge set to 'Millie Miley' Type Of Permit set to 'Hot Work' Name Of Requestor set to 'Curley Benedict' Shift set to 'Second Shift' Work Permit Date Start set to '27-Mar-2026' Work Permit Date End set to '27-Mar-2026' Work Permit Time Start set to '02:00 PM' Work Permit Time End set to '10:00 PM' Is Manual Ptw set to 'False' Status set to 'Submit'	NA