

Incident Report - (Incident UID - IMF/TTK/COI/IAP/25/00074)

Incident Information

Incident UID	IMF/TTK/COI/IAP/25/00074	Category Name	Injury-same as prod- don't delete
Status	FIRReleased	Site Name	Coimbatore
Department Nam e	Polishing	Incident Date & T ime	18-Nov-2025 12:00 AM
Created On	19-Nov-2025 04:57 PM	Reported By	Lalit Aditya Kola

Incident Description

"Operator injured his left thumb while adjusting the polishing machine fixture. The thumb got pinched between the clamp and the metal pla te during manual alignment. The supervisor immediately stopped the machine and provided first aid."

Sections

Level of Injury	C L1-Bruise
	C L2-Abrasion
	C L3-Burn
	L4-Laceration
	C L5-Fracture
	C L6-Amputation

Photograph of injury & machine

Attach: 1

Attachments



Injury treatment details

Number of people injured:: 1	Details of treatment given & doctor's ad vice:: "Wound cleaned with antiseptic, press ure dressing done to stop bleeding. Pain reli ef ointment applied. Advised to avoid workin g with sharp or heavy equipment for 48 hour
	s and return for dressing change."

Injured person details

Name of the injured person: R avi Prakash	Gender: Male		If Off role, mention the contra ctor name::
1 0	No. of Year's total experience in TTK Prestige : 5	machine: 2	Injury Happened in Which Shift?: Morning Shift (06:00 AM – 0 2:00 PM)

Attachments



Investigation Team

Name	

Incident History

Created On	Updated By	Comment	Attachments
19-Nov-2025 0 5:32 PM	Lalit Aditya Kola	Incident Status has been updated to 'FIRReleased'	
19-Nov-2025 0 5:29 PM	Lalit Aditya Kola	Incident Status has been updated to 'Validated'	
19-Nov-2025 0 5:11 PM	Lalit Aditya Kola	Sequence has been updated to '1' Sequence has been updated to '2' Sequence has been updated to '3'	
19-Nov-2025 0 5:11 PM	Lalit Aditya Kola	Incident Status has been updated to 'Submit'	
19-Nov-2025 0 4:57 PM	Lalit Aditya Kola	A new record was created: Incident Description set to ""Operator injured his left thumb while adjusting the polishing machine fixture. The thumb got pinc hed between the clamp and the metal plate during manual alignment. The supervisor immediately stopped the machine and provided first aid." Site N ame set to 'Coimbatore' Category Name set to 'Injury-same as prod- don't delete' Department Name set to 'Polishing' Status set to 'Draft' Incident Dat e Time set to '18-Nov-2025 12:00:00 AM'	

Definition:

Injury Type	Level	Definition
Bruise	L1	Blood Clot
Abrasion	L2	Skin Rubbed with Rough Surface
Burn	L3	Skin Burn due to fire, chemical, etc
Laceration	L4	Tear or a cut in the skin
Fracture	L5	Bone Damage
Amputation	L6	Loss of body part