

**Incident Report - (Incident UID - IMF/TTK/COI/IAP/25/00037)**

**Incident Information**

<b>Incident UID</b>	IMF/TTK/COI/IAP/25/00037	<b>Category Name</b>	Injury-same as prod- don't delete
<b>Incident Description</b>	An operator touched a hot surface of a heat-sealing machine during preventive maintenance, resulting in a minor burn on the palm.	<b>Status</b>	FinalReportReleased
<b>Site Name</b>	Coimbatore	<b>Department Name</b>	Maintenance
<b>Incident Date &amp; Time</b>	01-Oct-2025 07:45:00 AM	<b>Created On</b>	07-Oct-2025 11:21:10 AM
<b>Reported By</b>	Lalit Aditya Kola		

**Sections**

<b>Level of Injury</b>	<input type="radio"/> L1-Bruise <input type="radio"/> L2-Abrasion <input checked="" type="radio"/> L3-Burn <input type="radio"/> L4-Laceration <input type="radio"/> L5-Fracture <input type="radio"/> L6-Amputation
------------------------	---

**Photograph of injury & machine**

: 0

**Attachments**



**Injury treatment details**

<b>Number of people injured::</b> 1	<b>Treatment of Injury: Treated at OHC &amp; Referred for Diagnosis</b>	<b>Details of treatment given &amp; doctor's advice::</b> First-aid ointment applied; referred to EHS-approved clinic for follow-up to rule out blister formation.
-------------------------------------	---	--

**Injured person details**

<b>Name of the injured person:</b> Deepa S.	<b>Gender:</b> Female	<b>Role – ON / OFF:</b> Off Roll	<b>If Off role, mention the contractor name:</b> : R.K. Facility Services
<b>Age:</b> 32	<b>No. of Year's total experience in TTK Prestige :</b> 1 year	<b>No. of years in this process / machine :</b> 6 months	<b>Injury Happened in Which Shift?</b> : B Shift

**Attachments**

