

Is any Injury Occured

UID

Investigation Report - (Investigation UID - IR/TTK/AAA/25/00080)

Investigation Information

Investigation UID IR/TTK/AAA/25/00080		Investigation Category	Fire & others investigation report	
Investigation Status	Final Report Released	Created On	19-Nov-2025 05:45 PM	
Approver Names	Lalit Aditya Kola, Mounika OSM, Shreya Ved			

Incident Information

Incident UID	IMF/TTK/COI/TIT/25/00111	Incident Category	Fire and others	
Site Name	Coimbatore	Department Name	25 regression	
Process		Asset		
Incident Status	FinalReportReleased	Created On	19-Nov-2025 04:50 PM	
Reported By	Lalit Aditya Kola			

Incident Description

"A small electrical fire broke out in the packaging area near Machine-3 due to overheating of a loose wire connection. Smoke was noticed by the operator and the area supervisor immediately initiated the emergency response. The fire was controlled within 3 minutes using a CO₂ extinguisher. No injuries were reported."

Sections

Incident Description					"A small electrical	fire broke out in the		
	,					packaging area noverheating of a lowar noticed by the supervisor immed response. The fire	ear Machine-3 due to cose wire connection. Se operator and the are lately initiated the emele was controlled within CO ₂ extinguisher. No inj	a rgency 3
Details of Loss/Property Damage								
				Cost Est	imate			
List of Damage Property:			١	Value:				
			Occur	rence:- Re	petitive/New			
If Repetitive, Last date of Incident: If Repeti		If Repetitive	ve, Plant/Department:		If Repetitive, Line:			
	Ro	oot Cause An	alysis (Why-V	Why: Drill d	own till the Sy	stem Issue / Failure	e):	
Why:				Root Cause::				
			Re	views and	Learning			
Documents revised based on CAPA:				L	Lessons Learned:			
			F	Preventive	Actions			
UID		Site Name Car		Category	Name	Created By	Description	Status
TA/TTK/COI/INR/25/00208 Coimbatore		Investigation Report		Lalit Aditya Kola		Drafted		
		Horizont	al Deploymen	nt of Preve	ntive Actions	With in the Site		
UID	C	Site Name Category I		ategory Na	me	Created By	Description	Statue

Horizontal Deployment of Preventive Actions Across the Sites

Created By

Description Status

Category Name

Site Name