



Ticket Report

Organisation	Netskope Inc.
Ticket UID	T/VOS//25/00010
Status	Open
DueDate	17-Oct-2025
Site	Mount Repose
User Type	Employee
Department	Maintenance
Reported By	Annabel Whisenhunt
Mobile Number	+91 2000009798
Others Involved	NA
Category	Near Miss
Description	shopfloor lighting DB 14 door open, may chance of hit and fall.
What is the Exact Location	extrusion store entry left side
Ticket Image(s)	
Ticket Video(s)	NA
Ticket Audio(s)	NA
Ticket File(s)	NA
Created	17-Oct-2025 07:12:05 AM
Modified	17-Oct-2025 09:30:29 AM
Investigation Checklist	Question: Category of the Near Miss Answer: Slip/Trip/Fall
Assigned To	Mena Medley
Resolved On	NA

17-Oct-2025 07:12:05 AM - Annabel Whisenhunt: Uploaded 1 Attachment(s).

17-Oct-2025 07:12:05 AM - Annabel Whisenhunt: A new record was created: Uid set to 'T/VOS//25/00010'

17-Oct-2025 08:37:21 AM - Annabel Whisenhunt updated the status to Open

Ticket History

17-Oct-2025 09:30:29 AM - Mario Mattern: Department has been updated to 'Maintenance' Due Date has been updated to '16-Oct-2025'

17-Oct-2025 09:30:29 AM - Mario Mattern: Checklist Response for: Checklist - What is the Exact Location, updated to extrusion store entry left side. Checklist Response for: Description, updated to shopfloor lighting DB 14 door open, may chance of hit and fall..

To view all Audio(s)/Video(s)/Photo(s)/File(s), Visit:

<https://www.incidentreporter365.com/#/incidents/view/249/58369>

This is a computer generated report. For queries please mail to contact@oqsha.com