

Inspection Report - WATER TANKER (Inspection UID - I/TTK/COI/WTT/25/00002)

Inspection Information

Inspection Name	Water Tanker Inspection 002	Inspection Type	WATER TANKER
Inspection Status	Verified	Site Name	Coimbatore
Asset	NA	Non Oqsha Assets	

Sections

Checklist

1) Physical condition of vehicle is good and free from leakage.: No	2) No damage in tire (Bolts, crack, cuts & air pressure, etc.): No	3) Side mirror should be in good condition.: No	4) Head & tail light and indicators are in working condition.: No
5) Wiper should be in running condition.: No	6) Wind shield/glass should be in proper condition.: No	7) Seatbelt should be available.: No	8) Red triangle/Reflective tape should be fixed in front of vehicle.: No
9) Registration number should be written.: No	10) Front & reverse horn.: No	11) Fire extinguisher in operator cabin.: No	12) Operator have valid and suitable license.: No
13) First aid kit should be available.: No	14) Normal break & emergency (hand) break should be in functional & operational condition.: No		

Attachments



[OQSHA_Loto_v1_2025-09-02_11-32-22-3222_bb94898d-3be1-486e-b9bc-dd4b1187218a.pdf](#)

Inspection History

Created On	Created By	Comment	Attachments
02-Sep-2025 05:02:22 PM	Lalit Aditya Kola	A new record was created: Inspection Name set to 'Water Tanker Inspection 002' Inspection Type set to 'WATER TANKER' Status set to 'Verify' Site Name set to 'Coimbatore'	