

**Inspection Report - Fire Bucket Inspection Checklist (Inspection UID - I/MHC/GRR/FBI/26/00024)**

**Inspection Information**

<b>Inspection Type</b>	Fire Bucket Inspection Checklist	<b>Inspection Status</b>	Approved
<b>Site Name</b>	Alanreed	<b>Created on</b>	06-Mar-2026 11:54:59 AM
<b>Asset</b>	Fire Bucket	<b>Non Oqsha Assets</b>	
<b>Next Inspection Date</b>	06-Apr-2026 11:54:59 AM	<b>Next Inspection Overdue Days</b>	0

**Sections**

**Inspection checks**

<b>Company name:</b> My Home Constructions Private Limited	<b>Contractor name:</b> Nakka Phanindra Kumar EHS
--	---

<b>Attachments</b>
<a href="#">Image</a>

**Equipment Status**

<b>Equipment Status at Site:</b> In Site	<b>Equipment Usage Status:</b> In Usage
--	---

**Check Points**

<b>Is the bucket free from rust, dents, or cracks?:</b> Yes	<b>Is the bucket painted red with "FIRE" clearly marked in white lettering?:</b> Yes	<b>Is the bucket free from any contamination (e.g., oil, dirt, or debris)?:</b> Yes	<b>Is the handle securely attached and free from damage?:</b> Yes
<b>Does the bucket have a round bottom (for hanging, as per standards)?:</b> Yes	<b>Is the bucket filled with clean, dry sand or water, depending on its designated use?:</b> Yes	<b>Is the sand free from moisture, stones, or debris, and regularly stirred or replaced?:</b> Yes	<b>If water is used, is it clean and sufficient in quantity?:</b> Yes
<b>Is the bucket placed in a designated and easily accessible location?:</b> Yes	<b>Are fire buckets clearly marked with reflective tape or under adequate lighting?:</b> Yes	<b>Is the bucket securely hung on a stand or bracket?:</b> Yes	<b>Is the stand painted and free from rust or corrosion?:</b> Yes
<b>Are workers trained on the proper use of fire buckets?:</b> Yes	<b>Is an inspection log maintained with dates, findings, and corrective actions?:</b> Yes		

**Signatures**

<b>Inspected by:</b> Nakka Phanindra Kumar EHS at 06-Mar-2026 11:54 AM.	<b>Checked by:</b> Uma Mahesh Akki at 3/12/2026 5:04:51 PM.	<b>Verified by:</b> Srikanth Anumula MHC at 3/12/2026 5:51:12 PM.	<b>Approved by:</b> sravan kumar pakki at 3/12/2026 6:04:37 PM.
---	---	---	---

**Inspection History**

Created On	Created By	Comment	Attachments
12-Mar-2026 06:04:37 PM	Rena Kay	Status has been updated to 'Approve'	
12-Mar-2026 06:04:36 PM	Rena Kay	sravan kumar pakki has Approved.	
12-Mar-2026 05:51:12 PM	Racheal Piatt	Srikanth Anumula MHC has Verified.	
12-Mar-2026 05:51:12 PM	Racheal Piatt	Status has been updated to 'Verify'	
12-Mar-2026 05:51:12 PM	Racheal Piatt	Inspection has been assigned to sravan kumar pakki at the Approved by stage.	
12-Mar-2026 05:04:51 PM	Owens Strauss	Status has been updated to 'Check'	
12-Mar-2026 05:04:51 PM	Owens Strauss	Inspection has been assigned to Srikanth Anumula MHC at the Verified by stage.	
12-Mar-2026 05:04:50 PM	Owens Strauss	Uma Mahesh Akki has Checked.	
06-Mar-2026 11:54:59 AM	Caroline Su	A new record was created: Site set to 'Grava Residences' Asset Type set to 'Safety equipment' Inspection Type set to 'Fire Bucket Inspection Checklist' Status set to 'Inspection requested'	

06-Mar-2026 11:54:59 AM	Caroline Su	Inspection has been assigned to Uma Mahesh Akki at the Checked by stage.	
----------------------------	-------------	--	--