

Inspection Report - Angular Grinder Inspection Checklist (Inspection UID - I/MHC/GRR/AGI/26/00139)

Inspection Information

Inspection Type	Angular Grinder Inspection Checklist	Inspection Status	Approved
Site Name	Alanreed	Created on	18-Mar-2026 02:56:15 PM
Asset	Angular Grinder	Non Oqsha Assets	
Next Inspection Date	18-Apr-2026 02:56:15 PM	Next Inspection Overdue Days	0

Sections

Inspection checks

Company name: Guruleela Construction LLP	Contractor name: Krishna debnath
---	---

Attachments
Image

Equipment Status

Equipment Status at Site: In Site	Equipment Status at Site (Copy): In Usage
--	--

Check Points

1.Is body condition of machine with rear handle without damage and earthing of body & body type (fibre or metal)?: Yes	2.Is handle in good condition without any damage?: Yes	3.Is the wheel guard provided without any cracks, damage?: Yes	4.Is the trigger switch in proper condition?: Yes
5.Is cord strain reliever (cable glands) was good in condition without any damage?: Yes	6.Is suitable grinding or cutting wheel was in proper condition without any damage?: Yes	7.Is spindle locking button was in proper condition without any damage?: Yes	8.Is electric cable maintaining without any cuts and joints along with industrial plug top?: Yes
9.The no-volt release switch is in proper condition?: Yes	10.Is the suitable tool is using for fix the wheel?: Yes	11.Is there RPM of wheel is greater than motor wheel?: Yes	

Remarks

NA

Signatures

Inspected by: Krishna debnath at 18-Mar-2026 02:56 PM.	Checked by: Uma Mahesh Akki at 3/20/2026 6:10:37 PM.	Verified by: vaidya naik at 3/25/2026 3:28:39 PM.	Approved by: Nakka Phanindra Kumar EHS at 3/25/2026 3:32:28 PM.
---	---	--	--

Inspection History

Created On	Created By	Comment	Attachments
25-Mar-2026 03:32:28 PM	Caroline Su	Nakka Phanindra Kumar EHS has Approved.	
25-Mar-2026 03:32:28 PM	Caroline Su	Status has been updated to 'Approve'	
25-Mar-2026 03:28:39 PM	Loring Romero	Status has been updated to 'Verify'	
25-Mar-2026 03:28:39 PM	Loring Romero	Inspection has been assigned to Nakka Phanindra Kumar EHS at the Approved by stage.	
25-Mar-2026 03:28:38 PM	Loring Romero	vaidya naik has Verified.	
20-Mar-2026 06:10:37 PM	Owens Strauss	Uma Mahesh Akki has Checked.	
20-Mar-2026 06:10:37 PM	Owens Strauss	Status has been updated to 'Check'	
20-Mar-2026 06:10:37 PM	Owens Strauss	Inspection has been assigned to vaidya naik at the Verified by stage.	
18-Mar-2026 02:56:15 PM	Fidelia Real	A new record was created: Site set to 'Grava Residences' Asset Type set to 'Portable Electrical Tools' Inspection Type set to 'Angular Grinder Inspection Checklist' Status set to 'Inspection requested'	

18-Mar-2026 02:56:15 PM	Fidelia Real	Inspection has been assigned to Uma Mahesh Akki at the Checked by stage.	
----------------------------	--------------	--	--