

Inspection Report - Water Tanker (Inspection UID - I/TTK/COI/WTT/25/00034)

Inspection Information

Inspection Name	Inspection test	Inspection Type	Water Tanker
Inspection Status	Verified	Site Name	Coimbatore
Asset	NA	Non Oqsha Assets	
Due Date	27-Oct-2025		

Sections

Note: Please write Yes or No in the given box and if some comments write in remarks column.

: 0

1) Physical condition of vehicle is good and free from leakage.

Test: Yes	remarks: Value
-----------	----------------

Test

2) Side mirror should be in good condition: Yes	Remarks: Value
---	----------------

Inspection History

Created On	Created By	Comment	Attachments
23-Oct-2025 02:24:20 PM	Mounika Laissetti	Test has been updated to 'Option 1' 2) Side mirror should be in good condition has been updated to 'Option 1'	
23-Oct-2025 02:24:19 PM	Mounika Laissetti	Mounika Laissetti has Verified.	
23-Oct-2025 02:21:46 PM	Lalit Aditya Kola	A new record was created: Inspection Name set to 'Inspection test' Inspection Type set to 'Water Tanker' Status set to 'Planned' Site Name set to 'Coimbatore' Due Date set to '27-Oct-2025 05:30:00 AM'	