

Inspection Report - BENCH CUTTING MACHINE (Inspection UID - I/TTK/COI/BCM/25/00030)

Inspection Information

Inspection Name	safety	Inspection Type	BENCH CUTTING MACHINE
Inspection Status	Inspected	Site Name	Coimbatore
Asset	NA	Non Oqsha Assets	
Department	Maintenance	Due Date	29-Oct-2025

Sections

Checklist

1) Physical condition of body should be good & sound.: Yes	Remarks: NA	2) On/off switch should be in proper condition.: N/A	Remarks: NA
3) Fixed guard should be in good condition.: N/A	Remarks: NA	4) Auto adjustable guard should be functional condition.: N/A	Remarks: NA
5) Cutting wheel should free from defect and rotating capacity should be marked, standard quality of cutting wheel used.: N/A	Remarks: NA	6) Positioning screw should be in working condition.: N/A	Remarks: NA
7) Power cable should be free from damage and connection taken through industrial plug.: N/A	Remarks: NA		

Attachments
Image

Signature(s)

Signature 1: Signed by Shreya V at 31-Oct-2025 12:43 PM.	Signature 2: NA	Signature 3: NA
---	------------------------	------------------------

Inspection History

Created On	Created By	Comment	Attachments
31-Oct-2025 12:43:04 PM	Shreya Ved	A new record was created: Inspection Name set to 'safety' Inspection Type set to 'BENCH CUTTING MACHINE' Status set to 'Inspected' Site Name set to 'Coimbatore' Due Date set to '29-Oct-2025 05:30:00 AM'	