

Inspection Report - BENCH CUTTING MACHINE (Inspection UID - I/TTK/COI/BCM/25/00037)

Inspection Information

Inspection Name	test inspection name nov 7	Inspection Type	BENCH CUTTING MACHINE
Inspection Status	Inspected	Site Name	Coimbatore
Asset	NA	Non Oqsha Assets	assets
Department	25 regression		

Sections

Who are you

: shreya


Is inspection done

☒

Checklist

1) Physical condition of body should be good & sound.: No	Remarks: NA	2) On/off switch should be in proper condition.: No	Remarks: NA
3) Fixed guard should be in good condition.: No	Remarks: NA	4) Auto adjustable guard should be functional condition.: No	Remarks: NA
5) Cutting wheel should free from defect and rotating capacity should be marked, standard quality of cutting wheel used.: No	Remarks: NA	6) Positioning screw should be in working condition.: No	Remarks: NA
7) Power cable should be free from damage and connection taken through industrial plug.: No	Remarks: NA		

Attachments



Signature(s)

Signature 2: Signed by Shreya Ved at 11/7/2025 7:47:50 AM.

Inspection History

Created On	Created By	Comment	Attachments
07-Nov-2025 01:17:49 PM	Shreya Ved	Shreya Ved has Inspected.	
07-Nov-2025 01:17:04 PM	Shreya Ved	A new record was created: Inspection Name set to 'test inspection name nov 7' Inspection Type set to 'BENCH CUTTING MACHINE' Status set to 'Planned' Site Name set to 'Coimbatore' Non Oqsha Assets set to 'assets'	