



Inspection Report - BENCH CUTTING MACHINE (Inspection UID - I/TTK/COI/BCM/25/00043)

Inspection Information

Inspection Name	type management	Inspection Ivne	BENCH CUTTING MACHINE
Inspection Status	Draft	Site Name	Coimbatore
Asset	NA	Non Oqsha Assets	
Department	Maintenance	Due Date	24-Nov-2025

Sections

Who are you

· Supervice	-		
. Superviso			
'			

Is inspection done

Checklist

1) Physical condition of body should be good & sound.: Yes	Remarks: done	2) On/off switch should be in proper condition.: No	Remarks: no
3) Fixed guard should be in good condition.: No	Remarks: no	4) Auto adjustable guard should be functional condition.:	Remarks:
5) Cutting wheel should free from defect and rotating capacity should be marked, standard quality of cutting wheel used.:	Remarks:	6) Positioning screw should be in working condition.:	Remarks:
7) Power cable should be free from damage and connection taken through industrial plug.:	Remarks:		

Attachments			
"I CAN DO WHATEVER I WANT TODAY."			
TOAN DO WHATEVERT WART TODAT.			

Signature(s)

Signature 2: NA

Inspection History

		·	
Created On	Created By	Comment	Attachments
14-Nov-2025 02:10:21 PM	Lalit Aditya Kola	A new record was created: Inspection Name set to 'type management ' Inspection Type set to 'BENCH CUTTING MACHINE' Status set to 'Draft' Site Name set to 'Coimbatore' Due Date set to '24-Nov-2025 05:30:00 AM'	