

Inspection Report - Water Tanker 1 (Inspection UID - I/TTK/COI/WTT/25/00042)

Inspection Information

Inspection Name	portal	Inspection Type	Water Tanker 1
Inspection Status	Verified	Site Name	Coimbatore
Asset	NA	Non Oqsha Assets	
Department	Maintenance		

Sections

Note: Please write Yes or No in the given box and if some comments write in remarks column.

: 0

1) Physical condition of vehicle is good and free from leakage.

Test: Yes	remarks: Value
-----------	----------------

Test

2) Side mirror should be in good condition: No	Remarks: Value
--	----------------

Inspection History

Created On	Created By	Comment	Attachments
16-Nov-2025 02:47:46 PM	Shreya Ved	A new record was created: Inspection Name set to 'portal' Inspection Type set to 'Water Tanker 1' Status set to 'Verified' Site Name set to 'Coimbatore'	