

Inspection Report - BENCH CUTTING MACHINE (Inspection UID - I/TTK/COI/BCM/25/00052)

Inspection Information

Inspection Name	test inspection name nov 18	Inspection Type	BENCH CUTTING MACHINE
Inspection Status	Draft	Site Name	Coimbatore
Asset	NA	Non Oqsha Assets	
Department	Maintenance		

Sections

Who are you

: aefjhb


Is inspection done

☒

Checklist

1) Physical condition of body should be good & sound.: Yes	Remarks:	2) On/off switch should be in proper condition.: Yes	Remarks:
3) Fixed guard should be in good condition.: No	Remarks:	4) Auto adjustable guard should be functional condition.: N/A	Remarks:
5) Cutting wheel should free from defect and rotating capacity should be marked, standard quality of cutting wheel used.: No	Remarks:	6) Positioning screw should be in working condition.: Yes	Remarks:
7) Power cable should be free from damage and connection taken through industrial plug.:	Remarks:		

Attachments



Signature(s)

Signature 2: NA

Inspection History

Created On	Created By	Comment	Attachments
18-Nov-2025 01:01:00 PM	Lalit Aditya Kola	1) Physical condition of body should be good & sound. has been updated to 'Yes' 3) Fixed guard should be in good condition. has been updated to 'No' 4) Auto adjustable guard should be functional condition. has been updated to 'N/A' 5) Cutting wheel should free from defect and rotating capacity should be marked, standard quality of cutting wheel used. has been updated to 'No' 6) Positioning screw should be in working condition. has been updated to 'Yes'	
18-Nov-2025 01:00:58 PM	Lalit Aditya Kola	Lalit Aditya Kola has Draft.	
18-Nov-2025 01:00:48 PM	Lalit Aditya Kola	2) On/off switch should be in proper condition. has been updated to 'Yes'	

18-Nov-2025 01:00:47 PM	Lalit Aditya Kola	Lalit Aditya Kola has Draft.	
18-Nov-2025 01:00:41 PM	Lalit Aditya Kola	A new record was created: Inspection Name set to 'test inspection name nov 18' Inspection Type set to 'BENCH CUTTING MACHINE' Status set to 'Draft' Site Name set to 'Coimbatore'	