

Inspection Report - BENCH CUTTING MACHINE (Inspection UID - I/TTK/COI/BCM/26/00028)**Inspection Information**

Inspection Name	Test Inspection	Inspection Type	BENCH CUTTING MACHINE
Inspection Status	Verified	Site Name	Coimbatore
Asset	Test Asset	Non Oqsha Assets	NA
Department	Maintenance		

Sections**Checklist**

1) Physical condition of body should be good & sound.: 1	Remarks:	2) On/off switch should be in proper condition.:	Remarks:
3) Fixed guard should be in good condition.: 2	Remarks:	4) Auto adjustable guard should be functional condition.:	Remarks:
5) Cutting wheel should free from defect and rotating capacity should be marked, standard quality of cutting wheel used.: 2	Remarks:	6) Positioning screw should be in working condition.:	Remarks:
7) Power cable should be free from damage and connection taken through industrial plug.:	Remarks:		

Inspection History

Created On	Created By	Comment	Attachments
12-Feb-2026 12:25:35 PM	Rajkumar Pativada	A new record was created: Site set to 'Coimbatore' Department set to 'Maintenance' Inspection Name set to 'Test Inspection' Asset Type set to 'new asset types test' Inspection Type set to 'BENCH CUTTING MACHINE' Status set to 'Verified' Assigned To set to 'Abhinav Srivastava, christams sankranti'	