

Inspection Report - BENCH CUTTING MACHINE (Inspection UID - I/TTK/COI/BCM/26/00036)**Inspection Information**

Inspection Name	dvjgbhknjmk	Inspection Type	BENCH CUTTING MACHINE
Inspection Status	Verified	Site Name	Coimbatore
Asset	Asset 06-02 - new asset	Non Oqsha Assets	

Sections**Checklist**

1) Physical condition of body should be good & sound.: N/A	Remarks: NA	2) On/off switch should be in proper condition.: N/A	Remarks: NA
3) Fixed guard should be in good condition.: N/A	Remarks: NA	4) Auto adjustable guard should be functional condition.: N/A	Remarks: NA
5) Cutting wheel should free from defect and rotating capacity should be marked, standard quality of cutting wheel used.: N/A	Remarks: NA	6) Positioning screw should be in working condition.: N/A	Remarks: NA
7) Power cable should be free from damage and connection taken through industrial plug.: N/A	Remarks: NA		

Inspection History

Created On	Created By	Comment	Attachments
19-Feb-2026 01:20:03 PM	Rajkumar Pativada	A new record was created: Site set to 'Coimbatore' Inspection Name set to 'dvjgbhknjmk' Asset Type set to 'Asset 06-02' Inspection Type set to 'BENCH CUTTING MACHINE' Status set to 'Verified'	