

**Inspection Report - BENCH CUTTING MACHINE (Inspection UID - I/TTK/COI/BCM/26/00037)**
**Inspection Information**

<b>Inspection Name</b>	rcd	<b>Inspection Type</b>	BENCH CUTTING MACHINE
<b>Inspection Status</b>	Verified	<b>Site Name</b>	Coimbatore
<b>Asset</b>	Asset 06-02 - cdce	<b>Non Oqsha Assets</b>	

**Sections**
**Checklist**

<b>1) Physical condition of body should be good &amp; sound.: N/A</b>	Remarks: NA	<b>2) On/off switch should be in proper condition.: N/A</b>	Remarks: NA
<b>3) Fixed guard should be in good condition.: N/A</b>	Remarks: NA	<b>4) Auto adjustable guard should be functional condition.: N/A</b>	Remarks: NA
<b>5) Cutting wheel should free from defect and rotating capacity should be marked, standard quality of cutting wheel used.: N/A</b>	Remarks: NA	<b>6) Positioning screw should be in working condition.: N/A</b>	Remarks: NA
<b>7) Power cable should be free from damage and connection taken through industrial plug.: N/A</b>	Remarks: NA		

**Inspection History**

Created On	Created By	Comment	Attachments
19-Feb-2026 01:24:58 PM	Rajkumar Pativada	A new record was created: Site set to 'Coimbatore' Inspection Name set to 'rcd' Asset Type set to 'Asset 06-02' Inspection Type set to 'BENCH CUTTING MACHINE' Status set to 'Verified'	