

**Inspection Report - P&M - Chain Pulley Block Inspection Checklists (Inspection UID - I/APS/AVAP-C/26/00029)**

**Inspection Information**

<b>Inspection Type</b>	P&M - Chain Pulley Block Inspection Checklists	<b>Inspection Status</b>	Approved
<b>Site Name</b>	Avali	<b>Created on</b>	16-Mar-2026 08:48:36 PM
<b>Asset</b>	test	<b>Non Oqsha Assets</b>	NA
<b>Next Inspection Date</b>	16-Jun-2026 08:48:36 PM	<b>Next Inspection Overdue Days</b>	0

**Sections**

**Inspection checks**

<b>Company name:</b> My Home Private LTD	<b>Contractor name:</b> Palak Gupta	<b>Asset identification number:</b> NA	<b>Frequency:</b> NA
--	-------------------------------------	--	----------------------

**Attachments**

The attachment shows a 3D CAD model of a red chain pulley block. The model is displayed in a software interface with various toolbars and a file explorer on the left. The pulley block has a hook at the top and a central shaft with a groove for a chain. The model is rendered in a solid red color.

**Check Points**

<b>1.Is the chain pulley block is good condition &amp; working with TPI?:</b> N/A	<b>2.Is the chain is free from corrosion, defects, cracks, damage etc?:</b> N/A	<b>3.Is the hook point is in good condition? (not stretched more than 15% of its original shape):</b> N/A	<b>4.Are safety latch is working condition and placed into hook?:</b> N/A
<b>5.Is SWL (safe working load) is marked and visible?:</b> N/A	<b>6.Is all the rotating parts are covered?:</b> N/A	<b>7.Is sufficient lubrication has done?:</b> N/A	

**Equipment Status at Site**

<b>Equipment Status at Site:</b> NA	<b>Equipment Usage Status:</b> NA
-------------------------------------	-----------------------------------

**Signatures**

<b>Inspected:</b> Palak Gupta at 16-Mar-2026 08:48 PM.	<b>Checked:</b> Rajkumar Pativada at 3/16/2026 3:20:12 PM.	<b>Verified:</b> Rajkumar Pativada at 3/16/2026 3:20:22 PM.	<b>Approved:</b> Rajkumar Pativada at 3/16/2026 3:20:32 PM.
--	--	---	---

**Previous Inspections**

Inspection UID	Created on	Site	Due date	Overdue days	Status	Frequency
I/APS/AVAP-C/26/00031	16-Mar-2026 08:58:44 PM	Avali	16-Mar-2027	0	Approved	Yearly
I/APS/AVAP-C/26/00030	16-Mar-2026 08:54:46 PM	Avali	16-Sep-2026	0	Approved	HalfYearly
I/APS/AVAP-C/26/00028	16-Mar-2026 08:43:14 PM	Avali	16-Apr-2026	0	Approved	Monthly

**Inspection History**

Created On	Created By	Comment	Attachments
16-Mar-2026 08:50:32 PM	Rajkumar Pativada	Rajkumar Pativada has Approved.	
16-Mar-2026 08:50:32 PM	Rajkumar Pativada	Status has been updated to 'Approve' Equipment Usage Status has been updated to 'Equipment Usage Status'	
16-Mar-2026 08:50:22 PM	Rajkumar Pativada	Rajkumar Pativada has Verified.	

16-Mar-2026 08:50:22 PM	Rajkumar Pativada	Status has been updated to 'Verify'	
16-Mar-2026 08:50:22 PM	Rajkumar Pativada	Inspection has been assigned to Rajkumar Pativada at the Approved stage.	
16-Mar-2026 08:50:12 PM	Rajkumar Pativada	Rajkumar Pativada has Checked.	
16-Mar-2026 08:50:12 PM	Rajkumar Pativada	Status has been updated to 'Check'	
16-Mar-2026 08:50:12 PM	Rajkumar Pativada	Inspection has been assigned to Rajkumar Pativada at the Verified stage.	
16-Mar-2026 08:48:36 PM	Palak Gupta	A new record was created: Site set to 'Avali' Department set to 'EHS' Asset Type set to 'P & M' Inspection Type set to 'P&M - Chain Pulley Block Inspection Checklists' Status set to 'Inspected' Asset set to 'test'	
16-Mar-2026 08:48:36 PM	Palak Gupta	Inspection has been assigned to Rajkumar Pativada at the Checked stage.	