

**Inspection Report - P&M - Air Compressor Inspection Checklist(App) (Inspection UID - I/APS/AVAP-A/26/00004)**

**Inspection Information**

<b>Inspection Type</b>	P&M - Air Compressor Inspection Checklist(App)	<b>Inspection Status</b>	Inspected
<b>Site Name</b>	Avali	<b>Created on</b>	18-Mar-2026 09:48:52 AM
<b>Asset</b>	DEFAULT - CHAINPULLEY	<b>Non Oqsha Assets</b>	
<b>Next Inspection Date</b>	19-Mar-2026 09:48:52 AM	<b>Next Inspection Overdue Days</b>	2
<b>Department</b>	dept		

**Sections**

**Check Points**

<b>1.Is air compressor physically in good condition with TPI certificate?:</b> N/A	<b>2.Is motor physical condition is good and guard is provided to rotary part?:</b> N/A	<b>3.Is inspection date and due date was marked properly and visible?:</b> N/A	<b>4.Is piston was in good condition?:</b> N/A
<b>5.Is pressure gauge was free from defect and working in condition with calibration as per requirement?:</b> N/A	<b>6.Is safety valve was in working condition?:</b> N/A	<b>7.Is all other valves also tested and inspected as per legal requirements?:</b> N/A	<b>8.Is machine guarding was in good condition and attached all time while in operation?:</b> Yes
<b>9.Is electrical connection allowed through industrial plug only?:</b> Yes	<b>10.Is all power cables are free from defects?:</b> Yes		

**Signatures**

<b>Inspected by (P&amp;M Dept.):</b> Rajkumar Pativada at 18-Mar-2026 09:48 AM.	<b>Checked by (Tower in-charge):</b> NA	<b>Verified by (Safety in-charge):</b> NA
---	---	---

**Inspection History**

<b>Created On</b>	<b>Created By</b>	<b>Comment</b>	<b>Attachments</b>
18-Mar-2026 09:48:52 AM	Rajkumar Pativada	A new record was created: Site set to 'Avali' Department set to 'dept' Asset Type set to 'DEFAULT' Inspection Type set to 'P&M - Air Compressor Inspection Checklist(App)' Status set to 'Inspected'	
18-Mar-2026 09:48:52 AM	Rajkumar Pativada	Inspection has been assigned to Palak Gupta at the Checked by (Tower in-charge) stage.	