

Inspection Report - P&M - Air Compressor Inspection Checklist(App) (Inspection UID - I/APS/APP/P-A/26/00008)

Inspection Information

Inspection Type	P&M - Air Compressor Inspection Checklist(App)	Inspection Status	Inspected
Site Name	Apas	Created on	18-Mar-2026 09:42:01 PM
Asset	DEFAULT - CHAINPULLEY	Non Oqsha Assets	
Next Inspection Date	25-Mar-2026 09:42:01 PM	Next Inspection Overdue Days	0

Sections

Check Points

1.Is air compressor physically in good condition with TPI certificate?: N/A	2.Is motor physical condition is good and guard is provided to rotary part?: N/A	3.Is inspection date and due date was marked properly and visible?: N/A	4.Is piston was in good condition?: N/A
5.Is pressure gauge was free from defect and working in condition with calibration as per requirement?: N/A	6.Is safety valve was in working condition?: N/A	7.Is all other valves also tested and inspected as per legal requirements?: N/A	8.Is machine guarding was in good condition and attached all time while in operation?: N/A
9.Is electrical connection allowed through industrial plug only?: N/A	10.Is all power cables are free from defects?: N/A		

Signatures

Inspected by (P&M Dept.): Rajkumar Pativada at 18-Mar-2026 09:42 PM.	Checked by (Tower in-charge): NA	Verified by (Safety in-charge): NA
---	---	---

Previous Inspections

Inspection UID	Created on	Site	Due date	Overdue days	Status	Frequency
I/APS/APP/P-C/26/00169	18-Mar-2026 10:05:55 AM	Apas	19-Mar-2026	0	Inspected	Daily

Inspection History

Created On	Created By	Comment	Attachments
18-Mar-2026 09:42:01 PM	Rajkumar Pativada	A new record was created: Site set to 'Apas' Asset Type set to 'DEFAULT' Inspection Type set to 'P&M - Air Compressor Inspection Checklist(App)' Status set to 'Inspected' Asset set to 'DEFAULT - CHAINPULLEY'	
18-Mar-2026 09:42:01 PM	Rajkumar Pativada	Inspection has been assigned to Palak Gupta at the Checked by (Tower in-charge) stage.	