

**Inspection Report - Fire Extinguisher Inspection Checklist (Inspection UID - I/MHC/GRR/FEI/26/00010)**

**Inspection Information**

<b>Inspection Type</b>	Fire Extinguisher Inspection Checklist	<b>Inspection Status</b>	Checked
<b>Site Name</b>	Alanreed	<b>Created on</b>	06-Feb-2026 12:09:04 PM
<b>Asset</b>	CO2-FIRE EXTINGUISHER	<b>Non Oqsha Assets</b>	
<b>Next Inspection Date</b>	06-Mar-2026 12:09:04 PM	<b>Next Inspection Overdue Days</b>	26
<b>Due Date</b>	24-Mar-2026		

**Sections**

**Inspection checks**

<b>Company name:</b> My Home Constructions Private Limited	<b>Contractor name:</b> Nakka Phanindra Kumar EHS
--	---

<b>Attachments</b>
<a href="#">Image</a>

**Equipment Status**

<b>Equipment Status at Site:</b> In Site	<b>Equipment Usage Status:</b> In Usage
--	---

**Check Points**

<b>Is fire extinguisher being physically in good condition, including there is no signs of damage, corrosion or tempering?:</b> Yes	<b>Is temper seal is intact with pin available without any damage and not tempered and nothing was used in place of the pin?:</b> Yes	<b>Is discharge hose/Nozzle was in good condition without clogged, crack or broken. And is it free from leakage?:</b> Yes	<b>Is handle of fire extinguisher was intact and firm?:</b> Yes
<b>Is label, type of fire extinguisher and instruction are available and easy to read?:</b> Yes	<b>Is fire extinguisher was fully charged and pressure gauge is in green position?:</b> Yes	<b>Is fire extinguisher has mounted or placed in free of obstacles place and visible location? (above 40lbs should mounted 3.5feet level only):</b> Yes	<b>Is fire extinguisher having valid inspection and maintenance tag? If not so, need to replace that fire extinguisher.:</b> Yes

**Signatures**

<b>Inspected by:</b> Nakka Phanindra Kumar EHS at 06-Feb-2026 12:09 PM.	<b>Checked by:</b> Uma Mahesh Akki at 2/24/2026 2:02:17 PM.	<b>Verified by:</b> NA	<b>Approved by:</b> NA
---	---	------------------------	------------------------

**Inspection History**

Created On	Created By	Comment	Attachments
24-Feb-2026 02:02:17 PM	Owens Strauss	Uma Mahesh Akki has Checked.	
24-Feb-2026 02:02:17 PM	Owens Strauss	Status has been updated to 'Check'	
24-Feb-2026 02:02:17 PM	Owens Strauss	Inspection has been assigned to Srikanth Anumula MHC at the Verified by stage.	
06-Feb-2026 12:09:04 PM	Caroline Su	A new record was created: Site set to 'Grava Residences' Asset Type set to 'Safety equipment' Inspection Type set to 'Fire Extinguisher Inspection Checklist' Status set to 'Inspection requested'	
06-Feb-2026 12:09:04 PM	Caroline Su	Inspection has been assigned to Uma Mahesh Akki at the Checked by stage.	