



Inspection Report - Bar bending (Inspection UID - 22d2a270-faad-4701-b6d8-942cadd6424d)

Inspection Information

Inspection Name	bar check	Inspection Type	Bar bending
Inspection Status	Inspected	Site Name	Aparna New Site
Asset	NA	Non Oqsha Assets	bar

Sections

Checkpoints

Is Bar Bending Machine physically being condition good? (machine is Nosie free): Yes	Is machine provided with electrician & operation contact details?: NA	Is the machine earthing and body earthing is provided properly?: NA	Is the electrical connection taken through industrial plug only?: Yes
Is the machine fixed on ground properly to avoid movement while in operation?: Yes	Is the operating leaver insulated by non-conductive material?: Yes		

Signatures

Inspected by (Electrical Dept.): Signed by Sayan Mondal at 5/2/2025 10:12:00 PM.	Checked by (Tower in-charge): NA	Verified by (Safety in-charge): NA
--	----------------------------------	------------------------------------

Attachments

Type	Value
Audio	NA
Video	NA
Images	NA
File	NA

Inspection History

Created On	Created By	Comment	Attachments
20-Jun-2025 12:41:34 PM	Rajkumar Pativada	Value has been updated to '1'	