



Full Body Harness <a> □</a>

Other PPEs:

Doc No: MHCPL-EHS-PTW-16

Ankle Press Button shoes □

Cover All □

Goggles □

### Permit To Work Report - De-shuttering Work (Permit UID - APA/SPO/ABCCON/DW/0002)

### **Permit Information**

Type of permit	Name of project/site	Contractor company	Name of client/contractor	
De-shuttering Work	ring Work Sports ground Abc Constructions Raj Kumar Pativada		Raj Kumar Pativada	
Work Information				
	2/25/2025 12:00:00 AM /			

Start date / Close Date	2/25/2025 12:00:00 AM / 2/25/2025 12:00:00 AM	Work location	Hyderabad
Start time / End time	2/25/2025 10:31:00 AM / 2/25/2025 10:40:00 AM	Reference permit no.	
No. of workers	0	Tools/ equipment to be used	
Scope of work	scope of work in site or block		
Description of work			

#### **Sections**

## Hazards

Hazards				
Cave-In's	Falls into Excavation	Soil Contamination	Person Falls	
Electrical Shock	Hit by Vehicle □	Dust 🗆	Damage to Utilities ☐	
Water Ingression	Other Hazards:	Falling Materials	Fall of Person	
Unsafe Working Platform	Improper Handling of Materials	Scaffold Collapse	Slip, Trip & Fall □	
Poor Housekeeping				
	Precaution	ons Taken		
Other Precautions:	Good Access / Egress	Maintained Slope Angle	Edge Barricading ☐	
HIRA Undertaken	Good Housekeeping   ☐	Ladder Provided ☐	Deep-Excavation Signage's □	
Awareness on expected emergencies ? □	Area Barricading □	Safe working platform	Adequate illumination	
Provide Safety Nets	Proper Supervision	Safe Access / Egress		
Toolbox Talks				
Topics discussed:		Attach photo: 0		
Job Specific PPEs				
Safety Helmet	Safety Shoes	H.V. Vest	Gum Boots	

# Cotton Hand Gloves ☐ Face Shield ☐

Other PPE's:

Safety Considerations				
Make sure the excavated area shall be barricaded and place appropriate signage near the excavation.: <b>No</b>	Excavation shall be carried out under the guidance of a competent person as per engineers drawing.: <b>No</b>	Job specific training shall be carried out for the work force involved in the excavation activity by site safety person.: <b>No</b>	Excavated soil shall be placed 2m away from the excavation pit.:	
Communication between operator and flagman shall be visible and audible with adequate lighting during night work.: <b>No</b>	All the employees, operators and workforce shall use PPE.: <b>No</b>	Any other requirement (If Yes, please specify): Emergency exit are available. Emergency vehicle and First-aid provider shall be assured during the work.: <b>No</b>	Workers must be provided with safe access to the work.: <b>No</b>	
Acrophobia test of worker. (Height Phobia etc.): <b>No</b>	De-shuttering materials should be kept away properly in working areas: <b>No</b>	Do not overload the working platform with materials.: <b>No</b>	Ensure adequate supervision and experienced carpenters for safe works.: <b>No</b>	
Ensure proper scaffolding working platform is used.: <b>No</b>	The de-Shuttering area should be barricaded before starting work.: <b>No</b>	Inspection of working scaffolds, ladders, ramps and crossings.: <b>No</b>	Maintenance of good housekeeping around the working area and Access.: <b>No</b>	

Avoid throwing shuttering materials from a height.: <b>No</b>	Using a Pulley & rope system to lower the de-shuttering materials.: <b>No</b>		Safety training of workmen involved in formwork?: <b>No</b>
Removal of all unused and hanging forms, loose materials, etc.: <b>No</b>		Construction loads not placed on the freshly cast slab while removal of formwork.: <b>No</b>	

### Approval and authorization

Requestor	Issuer	Approver	Reviewer
Name: Raj Kumar Pativada	Name: Lalit Issuer	Name: Harsha THD	Name: Sayan Reviewer
Phone: +919160948627	Phone: +917993748764	Phone: +918555849483	Phone: +919898989898
Requested On: 25-Feb-2025	Issued On: 25-Feb-2025	Approved On: 25-Feb-2025	Reviewed On: 25-Feb-2025
10:31:11 AM	10:33:19 AM	10:34:17 AM	10:35:03 AM

### **Permit To Work Closure**

Check 1 □	Check 2: NA	Check 4: No	Check 6 □
Check 7: 0			
Check 3:	Check 5:		

## **Permit To Work History**

Created On	Created By	Comment	Attachments
25-Feb-2025 10:35:03 AM	Sayan Reviewer	The status has changed to Reviewed -4.	
25-Feb-2025 10:34:17 AM	Harsha THD	The status has changed to Approved -1. Assigned Reviewer: Sayan Reviewer	
25-Feb-2025 10:33:19 AM	Lalit Issuer	The status has changed to Issued -2. Assigned Approver: Harsha THD	
25-Feb-2025 10:31:11 AM	Raj Kumar Pativada	The status has changed to Requested -3. Assigned Issuer: Lalit Issuer	