Doc No: MHC-EHS-PTW-10



Permit To Work Report - Concrete Work (Permit UID - MHC/GRA/BSR/CW/0112)

Permit Information

Type of permit	Name of project/site	Contractor company	Name of client/contractor
Concrete Work	Grava	BSR Infra Ventures Private Ltd	Lalit Requestor

Work Information


Start date / Close Date	3/27/2025 12:00:00 AM / 3/27/2025 12:00:00 AM	Work location	safety location
Start time / End time	3/27/2025 11:39:00 AM / 3/28/2025 4:59:00 AM	Reference permit no.	11
No. of workers	11	Tools/ equipment to be used	safety
Scope of work	safety scope		
Description of work	safety description		

Sections

Hazards

Contact with Eyes □	Skin Contact	Inhalation	Electrical Shock
Hit by Vehicle ✓	Scaffold Collapse	Slip, Trip & Fall 🔽	Hit by Boom □
Other Hazards:			

Attachments






Precautions Taken

Good Access / Egress □	Scaffolding & working Platform	Adequate illumination	HIRA Undertaken □
Good Housekeeping 🗸	Ladder Provided □	Mobile Scaffolding ✓	Awareness on expected emergencies ? □
Other Precautions:			


Attachments



Toolbox Talks

Topics discussed: Attach photo: 1


Attachments




Job Specific PPEs

Safety Helmet	Safety Shoes	Full Body Harness	Cover All
Rubber Hand Gloves 🔽	Gum Boots 🗌	Goggles ✓	Face Shield
Other PPE's:			

Attachments






Safety Considerations

callety conclusions			
Required fall protection systems in place.: No	Workers using required fall protection systems.: No	Hoisting and rigging operations performed in a safe manner.: No	Guardrails in place and secure.: No
Rebar ends capped to prevent impaling.: No	Wearing safety glasses or goggles when pouring concrete?: No	Concrete washout water, collection, containment, disposal.: No	All workers have received basic Hazard Communication training?: No
MSDSs are available on the site for cement and related products used?: No	ELCB/RCCB provided for Needle Vibrators?: No	Proper Edge protection provided in concrete area?: No	All vibrators/lights electrical cables laid above 7' (feet) height?: No
Proper Access/egress provided in concrete pour area?: No	Is Proper Bracing provide for slab supporting props/Posts?: Yes	Is Eye Wash area provided near to concrete poring area?: Yes	Verification of Pumping equipment's are inspected prior to start?: Yes

Attachments



Approval and authorization

Requester	Issuer	Approver	Reviewer
Name: Lalit Requestor	Name: Lalit -iSSUER	Name: Lalit -Approver	Name: Lalit -Reviewer
Phone: +91999999990	Phone: +91999999900	Phone: +919988778899	Phone: +911122112211
Time: 27-Mar-2025 11:39:40	Time: 27-Mar-2025 11:42:10	Time: 27-Mar-2025 11:46:18	Time: 27-Mar-2025 11:48:50
AM	AM	AM	AM

Extension UID: 8UVQL4

Extension Conditions		
Is sufficient Illumination to be provided	Yes	
Is security notified of night work	Yes	
Is medical aid resources available	Yes	
Availability & Use of PPE?s	Yes	
Proper Housekeeping to be done on daily basis	No	
Any other requirement (If Yes, please specify): Emergency exit are available, Emergency vehicle and First-aid provider shall be assured during the work Main Isolation Switch location is known to All	No	
Use of Full body harness with double lanyard & life line or anchor point (while doing hot work at height).	No	

Requester	Issuer	Approver	Reviewer
Name: Lalit Requestor	Name: Lalit -iSSUER	Name: Lalit -Approver	Name: Lalit -Reviewer
Mobile: +919999999990	Mobile: +91999999900	Mobile: +919988778899	Mobile: +911122112211
Time: 27-Mar-2025 12:03:31	Time: 27-Mar-2025 12:05:30	Time: 27-Mar-2025 12:09:57	Time: 27-Mar-2025 12:10:52
PM	PM	PM	PM
Duration: 5 hour(s)	Duration: 5 hour(s)	Duration: 5 hour(s)	Duration: 5 hour(s)

Permit To Work History

Created On	Created By	Comment	Attachments
27-Mar-2025 12:10:52 PM	Lalit -Reviewer	safety.	
27-Mar-2025 12:10:52 PM	Lalit -Reviewer	The status has changed to Extension Reviewed.	
27-Mar-2025 12:09:57 PM	Lalit -Approver	The status has changed to Extension Approved. Assigned Reviewer: Lalit - Reviewer	
27-Mar-2025 12:05:30 PM	Lalit -iSSUER	The status has changed to Extension Issued. Assigned Approver: Lalit - Approver	
27-Mar-2025 12:03:31 PM	Lalit Requestor	The status has changed to Extension Requested. Assigned Issuer: Lalit - iSSUER Duration: 5 hour(s).	
27-Mar-2025 11:48:50 AM	Lalit -Reviewer	safety. The status has changed to Reviewed.	
27-Mar-2025 11:48:50 AM	Lalit -Reviewer	Following changes are made in the PTW data: WorkLocation: safety location ScopeOfWork: safety scope WorkDescription: safety description	
27-Mar-2025 11:46:18 AM	Lalit -Approver	The status has changed to Approved. Assigned Reviewer: Lalit -Reviewer	
27-Mar-2025 11:46:17 AM	Lalit -Approver	Following changes are made in the PTW data: ScopeOfWork: safety 1	
27-Mar-2025 11:42:09 AM	Lalit -iSSUER	safety. The status has changed to Issued.	
27-Mar-2025 11:42:09 AM	Lalit -iSSUER	Section: Toolbox Talks Attach photo - 1	
27-Mar-2025 11:39:40 AM	Lalit Requestor	The status has changed to Requested. Assigned Issuer: Lalit -iSSUER	