Doc No: MHC-EHS-PTW-10



# Permit To Work Report - Concrete Work (Permit UID - MHC/GRA/BSR/CW/0114)

### **Permit Information**

Type of permit	Name of project/site	Contractor company	Name of client/contractor
Concrete Work	Grava	BSR Infra Ventures Private Ltd	Lalit Requestor

#### **Work Information**

Start date / Close Date	27-Mar-2025 / 27-Mar-2025	Work location	
Start time / End time	05:40:00 PM / 04:59:00 AM	Reference permit no.	
No. of workers	NA	Tools/ equipment to be used	
Scope of work			
Description of work			

#### Sections

#### Hazards

Contact with Eyes □	Skin Contact	Inhalation	Electrical Shock
Hit by Vehicle □	Scaffold Collapse □	Slip, Trip & Fall ☐	Hit by Boom □
Other Hazards:			

#### **Precautions Taken**

Good Access / Egress □	Scaffolding & working Platform $\square$	Adequate illumination	HIRA Undertaken □
Good Housekeeping ☐	Ladder Provided	I Monile Scattolding I	Awareness on expected emergencies ? □
Other Precautions:			_

### **Toolbox Talks**

Topics discussed:	Attach photo:

### Job Specific PPEs

Safety Helmet □	Safety Shoes	Full Body Harness	Cover All
Rubber Hand Gloves	Gum Boots	Goggles □	Face Shield
Other PPE's:			

## **Safety Considerations**

Required fall protection systems in place.: <b>No</b>	Workers using required fall protection systems.: <b>No</b>	Hoisting and rigging operations performed in a safe manner.: <b>No</b>	Guardrails in place and secure.: <b>No</b>
Rebar ends capped to prevent impaling.: <b>No</b>	Wearing safety glasses or goggles when pouring concrete?: <b>No</b>	Concrete washout water, collection, containment, disposal.: <b>No</b>	All workers have received basic Hazard Communication training?: <b>No</b>
MSDSs are available on the site for cement and related products used?: <b>No</b>	ELCB/RCCB provided for Needle Vibrators?: <b>No</b>	Proper Edge protection provided in concrete area?: <b>No</b>	All vibrators/lights electrical cables laid above 7' (feet) height?: <b>No</b>
Proper Access/egress provided in concrete pour area?: <b>No</b>		Is Eye Wash area provided near to concrete poring area?: <b>No</b>	Verification of Pumping equipment's are inspected prior to start?: <b>No</b>

### Approval and authorization

Requester	Issuer	Approver	Reviewer
Name: Lalit Requestor	Name: Lalit -iSSUER	Name: Lalit -Approver	Name: Lalit -Reviewer
Phone: +91999999990	Phone: +91999999900	Phone: +919988778899	Phone: +911122112211
Time: 27-Mar-2025 05:41:16	Time: 27-Mar-2025 05:42:14	Time: 27-Mar-2025 05:43:30	Time: 27-Mar-2025 05:44:39
PM	PM	PM	PM

### Extension UID: H4HOLU

Extension Conditions	
Is sufficient Illumination to be provided	No

Is security notified of night work	No
Is medical aid resources available	No
Availability & Use of PPE?s	No
Proper Housekeeping to be done on daily basis	No
Any other requirement (If Yes, please specify): Emergency exit are available, Emergency vehicle and First-aid provider shall be assured during the work Main Isolation Switch location is known to All	No
Use of Full body harness with double lanyard & life line or anchor point (while doing hot work at height).	No

Requester	Issuer	Approver	Reviewer
Name: Lalit Requestor	Name: Lalit -iSSUER	Name: Lalit -Approver	Name: Lalit -Reviewer
Mobile: +919999999990	Mobile: +91999999900	Mobile: +919988778899	Mobile: +911122112211
Time: 27-Mar-2025 05:46:51	Time: 27-Mar-2025 05:47:38	Time: 27-Mar-2025 05:48:42	Time: 27-Mar-2025 05:49:40
PM	PM	PM	PM
Duration: 5 hour(s)	Duration: 5 hour(s)	Duration: 5 hour(s)	Duration: 5 hour(s)

# **Permit To Work History**

Created On	Created By	Comment	Attachments
27-Mar-2025 05:49:40 PM	Lalit -Reviewer	The status has changed to Extension Reviewed.	
27-Mar-2025 05:48:42 PM	Lalit -Approver	The status has changed to Extension Approved. Assigned Reviewer: Lalit - Reviewer	
27-Mar-2025 05:47:38 PM	Lalit -iSSUER	The status has changed to Extension Issued. Assigned Approver: Lalit - Approver	
27-Mar-2025 05:46:52 PM	Lalit Requestor	The status has changed to Extension Requested. Assigned Issuer: Lalit - iSSUER Duration: 5 hour(s).	
27-Mar-2025 05:44:39 PM	Lalit -Reviewer	The status has changed to Reviewed.	
27-Mar-2025 05:43:30 PM	Lalit -Approver	The status has changed to Approved. Assigned Reviewer: Lalit -Reviewer	
27-Mar-2025 05:42:14 PM	Lalit -iSSUER	The status has changed to Issued. Assigned Approver: Lalit -Approver	
27-Mar-2025 05:41:16 PM	Lalit Requestor	The status has changed to Requested. Assigned Issuer: Lalit -iSSUER	