

PSSR Report (PSSR UID - P/TTK/COI/26/00022)



**PSSR Details**

<b>PSSR UID</b>	P/TTK/COI/26/00022	<b>Status</b>	PSSR In Progress
<b>Site</b>	Coimbatore	<b>Initiated By</b>	Rajkumar Pativada
<b>Location</b>		<b>Department</b>	Maintenance
<b>Associated MOC</b>	M/TTK/COI/(Ne/26/00018	<b>PSSR team</b>	Shreya V, Sagar EHS Head, Kushwanth Immidisetty
<b>Created On</b>	12-Feb-2026 03:49 PM	<b>Modified On</b>	12-Feb-2026 03:49 PM

**PSSR Checklist**

S.No	Check	Response	Remarks
1	Have all known new, existing, or potentially existing hazards been evaluated and mitigated?	Yes	N/A
2	Training Program conducted to the stakeholder	Yes	N/A
3	On the Job training conducted to the people going to work?	Yes	N/A
4	New SoP written and approved?	Yes	N/A
5	Have all affected personnel been notified and trained on the change?	Yes	N/A
6	Have you updated your emergency plan, if applicable?	Yes	N/A
7	Has all legal requirements are full filled?	Yes	N/A
8	Is Safety audit Conducted for the Machine / Layout & Observations Listed Below?	Yes	N/A

**Associated MoC details**

Site	Department	MoC Type	MoC Short Description	Initiated By	Created On	Location / Line
Coimbatore	Maintenance	(New) Layout Design	12-feb-2026_V1	Rajkumar Pativada	12-Feb-2026 03:45 PM	

**PSSR History**

Created On	Created By	Comment	Attachments
12-Feb-2026 03:49 PM	Rajkumar Pativada	A new record was created: Site Name set to 'Coimbatore' Department set to 'Maintenance' Associated Moc set to 'M/TTK/COI/(Ne/26/00018' Status set to 'PSSR In Progress' Initiated By Name set to 'Rajkumar Pativada' Approvers set to 'Shreya V (), Sagar EHS Head (), Kushwanth Immidisetty ()'	

To view this PSSR in full, visit: <https://qa-staging-2.oqsha.com/#/pssr/view/387/548>  
This is a computer-generated report. For queries please mail to [contact@oqsha.com](mailto:contact@oqsha.com)