

Safety Alert Report

| | |
|-------------------------|--|
| Organisation | Kura Oncology Inc. |
| Safety Alert UID | T/TRS/UCC/26/00040 |
| Status | Open |
| DueDate | 28-Mar-2026 |
| Severity | Moderate |
| Site | Old Orchard |
| Area | Kankinara Shed |
| User Type | Employee |
| Department | Project |
| Reported By | Oli Barth |
| Mobile Number | +91 2000005822 |
| Others Involved | NA |
| Category | Unsafe Condition |
| Description | Electrical panel system cover damaged & hot work going on near the same. Required to cover the same. |
| Safety Alert Image(s) | Image 1 |
| Safety Alert Video(s) | NA |
| Safety Alert Audio(s) | NA |
| Safety Alert File(s) | NA |
| Created | 23-Mar-2026 10:32:45 AM |
| Modified | 23-Mar-2026 10:32:45 AM |
| Investigation Checklist | NA |
| Assigned To | Evangelina Shrewsbury |
| Resolved On | NA |
| Safety Alert History | <p>23-Mar-2026 10:32:45 AM - Oli Barth: A new record was created: Uid set to 'T/TRS/UCC/26/00040' Site set to 'TGH' Reported By set to 'Poulami Mondal' Category set to 'Unsafe Condition' Department set to 'Project' Assigned To set to 'Munna Aziz' Severity set to 'Moderate' Due Date set to '28-Mar-2026' Area set to 'Kankinara Shed'</p> <p>23-Mar-2026 10:32:48 AM - Oli Barth: Uploaded 1 Attachment(s).</p> |

To view all Audio(s)/Video(s)/Photo(s)/File(s), Visit:

<https://www.incidentreporter365.com/#/incidents/view/258/68946>

This is a computer generated report. For queries please mail to contact@oqsha.com