



# Ticket Report

Organisation	Galecto Inc.
Ticket UID	C08SKE
Status	Closed
DueDate	26-Mar-2026
Severity	Moderate
Site	Alanreed
Department	NA
Reported By	Zelpha Belt
Mobile Number	+91 2000005150
Others Involved	NA
Category	Unsafe Act
Description	18th floor pour 1 flat no 1 steel workers and mivan workers are working without safety balt and working on outer side
What is the Location	tower 03 18th floor flat no 1
Name of the contractor involved	bsr
Ticket Image(s)	<input type="text"/> <input type="text"/>
Ticket Video(s)	NA
Ticket Audio(s)	NA
Ticket File(s)	NA
Created	24-Mar-2026 05:46:02 PM
Modified	26-Mar-2026 07:31:58 PM
Investigation Checklist	Question: What action has been taken Answer: safety harness provided to the workers
Assigned To	Zelia Gee
Resolved On	25-Mar-2026 11:13:09 AM

---

24-Mar-2026 05:46:02 PM - Zelpha Belt: A new record was created: Uid set to 'C08SKE' Site set to 'Grava Residences' Reported By set to 'naresh Guguloth' Category set to 'Unsafe Act' Assigned To set to 'Prabhakar Rao Salana - BSR' Severity set to 'Moderate' Due Date set to '26-Mar-2026'

24-Mar-2026 05:46:28 PM - Zelpha Belt: Uploaded 4 Attachment(s).

25-Mar-2026 11:08:33 AM - Zelia Gee: safety harness provided to the workers

25-Mar-2026 11:08:33 AM - Zelia Gee: Ticket status updated to Resolved.

#### Ticket History

25-Mar-2026 11:09:21 AM - Zelia Gee: safety harness provided to the workers

25-Mar-2026 11:11:35 AM - Zelia Gee: safety harness provided to the workers

25-Mar-2026 11:12:23 AM - Zelia Gee: safety harness provided to the workers

25-Mar-2026 11:13:09 AM - Zelia Gee: safety harness provided to the workers

26-Mar-2026 07:31:58 PM - Phillip Gaffney: Ticket status updated to Closed.

---

To view all Audio(s)/Video(s)/Photo(s)/File(s), Visit:

<https://www.incidentreporter365.com/#/incidents/view/211/69075>

*This is a computer generated report. For queries please mail to [contact@oqsha.com](mailto:contact@oqsha.com)*