Work Permit Report - (Work Permit UID - WP/TTK/COI/HOK/25/00008)

Work Permit Information

| Work Permit UID | WP/TTK/COI/HOK/25/00008 | Category Name | Hot Work |
|-------------------|-------------------------|-----------------|----------------------------|
| Description | | Status | NA |
| Site Name | Coimbatore | Department Name | Maintenance |
| Location | NA | Initiated By | Raj Kumar Pativada |
| Start Date & Time | 12-Sep-2025 06:03:00 PM | End Date & Time | 12-Sep-2025 11:30:00 PM |
| Created On | 12-Sep-2025 06:04:01 PM | Due Date | 12-Sep-2025 12:00:00 AM |
| Contractor | NA | Shift | NA |

Sections

Standalone Checks

1. Hazards Identified

| Presence of Toxic Gas Fumes | Sharp Edges □ | Poor Lighting | Combustible Materials Nearby |
|---------------------------------------|---------------------------|----------------------------|------------------------------|
| Work near Over Head Electrical Line ☐ | Presence of Flammable Gas | Tripp Hazard ☐ | Static Electricity |
| Flammable Materials Nearby | Improper Access | Unguarded Opening | Slip Hazard □ |
| Steam | Oil Spillage Observed | Moving / Running Machinery | Confined Space □ |
| Excavation Collapse | Vibration | Height Work | Work on Fragile Roofs |
| Mechanical / Electrical Spark | Noise 🗆 | Pressurized Line | Other Hazard(s): NA |

2. Control Measures

| Has the equipment mechanically locked to avoid rotation?: No | Has the insulation of electrical equipment been checked before the work start? : No | Have all the hand tools inspected & green tag provided?: No | Have all flammable or combustible material been removed from work site (at least 3 meters away)?: No |
|---|--|---|---|
| Has proper ventilation & lighting provided?: No | Is Fire blanket required & provided?: No | Is fire hydrant & fire water pump system in operation: No | Is a fire extinguisher available and ready?: No |
| Is gas monitoring carrying for hot work carrying in flammable storage area?: No | Has a fire watch person been assigned while performing hot work? Name | If sparks fall to lower levels, has adequate protection been provided?: No | Has the work and adjacent areas been isolated with warning tapes and barricades.: No |
| Flashback arrestor provided on nozzle torch as well as on cylinder regulator: No | Monitor the Hot work area after completing of the work for 1 Hr Name | Is the people planned for hot work is well experience & trained: | Is general safety induction given to the people working in hot work area: No |
| Is the adequate PPEs listed in Section 3 is available with the work crew: No | If any of the above criteria required is not met, then do not issue the work permit.: NA | | |

3. Safety Equipment Requirement & PPE to be used

| Safety Glasses ✓ | Nose Mask / Respirators ✓ | Safety Harness / Lifeline 🔽 | Fire Extinguisher No. 🗸 |
|--------------------------|-----------------------------------|--------------------------------|---|
| Safety Shoes ✓ | Hand Gloves ✓ | Ear Plug/ Muff 🗸 | Scaffolds & Ladders 🔽 |
| LOTO 🗸 | Barricades &Warning Signs 🗸 | Face Shield / Welding Goggle 🔽 | Helmet ✓ |
| Forced Ventilation 🗸 | Apron 🗸 | Any Other: ✓ | LOTO Tag Reference No.: Safety Equipment Requirement & PPE to be used - Yes |

4. Work Permit Authorization

| EHS Officer / Coordinator: NA Plant Head Only for Hot Work, Roof Work & Confined Space |
|--|
|--|

Approvers

| Sequence | Name | Status |
|----------|-------------------|----------|
| 0 | Prashanth Kona | Approved |
| 1 | Bishal Mondal | Approved |
| 2 | Lalit Aditya Kola | Approved |

History

| Created On | Created By | Comment | Attachments |
|----------------------------|--------------------|---|-------------|
| 12-Sep-2025 12:48:52 PM | Bishal Mondal | Status has been updated to Rejected | |
| 12-Sep-2025 12:48:52 PM | Bishal Mondal | Rejecting | |
| 12-Sep-2025 12:46:43 PM | Prashanth Kona | Status has been updated to Partially Approved | |
| 12-Sep-2025 12:46:43 PM | Prashanth Kona | Approving | |
| 12-Sep-2025 12:38:13 PM | Prashanth Kona | Status has been updated to Rejected | |
| 12-Sep-2025 12:38:13 PM | Prashanth Kona | Rejecting as insufficient details of permit | |
| 12-Sep-2025 12:34:11 PM | Raj Kumar Pativada | Status has been updated to Submitted | |
| 12-Sep-2025 12:34:02 PM | Raj Kumar Pativada | A new record was created: Uid set to 'WP/TTK/COI/HOK/25/00008' Work Permit Status Name set to 'Draft' | |